

PRIMARY CORNER DESCRIPTION W.C. to 1/4 sec. cor. 23 & 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 19)

(South between secs. 23 and 24)

21.50 chs.

Set witness qr. sec. corner, from which

An Alder 12" dia., bears N.10°E., 80 lks. dist.

A Spruce 100" dia., bears S.3°W., 27 lks. dist.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #745, dated May 1, 1902 - (DCSO records Vol. 1 Page(s) 67)

(21.25 chs.)

Witness cor. bet. secs. 23 and 24, corner gone, witness trees standing and agree with notes furnished by the surveyor general. I reestablish the witness cor. by setting a sandstone, 20x12x4 ins., 14" in the ground, mkd. W C on NE. face, from which (old witnesses):

A Spruce 100" dia., bears S.3°W., 27 lks. dist.

An Alder 12" dia., bears N.10°E., 80 lks. dist.

Survey by W.G. Corbitt; B. Senn; Paul Krugur; N. Seethoff - For: Crown Zellerbach - March 30, 1943 - C.S. File 52/91

Found BTs at W.C. called for at 59.75 chs. (81.00 chs. - 21.25 chs. = 59.75) As bearing and dist. to BTs did not check and no corner stone found, I relocated W.C. on solid rock in Creek making cross 1" deep 6" long with nail at intersection, covered same with 5 rocks, top one mkd: W.C. 1943", from X bears:

Orig. 100" Spruce (really only 5 ft. DBH above spreading roots), S.3°W., 17.82 ft. to old blazed face, 18.00 ft. to nail above blaze. Scribed face partly rotted away only marks V left which may be part of W.C.

Orig. 12" Alder now 18" rotten snag with hole where scribe marks might have been, N.18°E., 50 ft. to nail in base of tree.

A square stake, crayon mkd. "1/16 S" stands NE about 80 ft. from W.C. I left 1 1/2" I.P. with this stake on line N. of W.C.