

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 23)

Set post cornr of secs. 11, 12, 13 and 14, from which
A Fir 20" dia., bears N.3°W., 212 lks. dist.
A Fir 20" dia., bears S.59°E., 36 lks. dist.
A Hemlock 4" dia., bears N.8°E., 50 lks. dist.
A Spruce 15" dia., bears S.88°W., 106 lks. dist.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #745, dated May 1, 1902 - (DCSO records Vol. 1 Page(s) 69 and 74)

(Page 69)
Being unable, after diligent search, to find any trace of the corner of secs. 11, 12, 13 and 14, or any witnesses thereto belonging.

(Page 74)
Mark a Spruce 8" dia., T20S S12 on the NE.; R12W S13 on the SE.; S14 on the SW.; and S11 on the NW. faces, with 4 notches on the S. and 1 notch on the E. sides. of the same, for cor. of secs. 11, 12, 13 and 14, from which
A Spruce 12" dia., bears N.60°E., 7 lks. dist. mkd. T20S R12W S12 BT.
A Spruce 30" dia., bears S.45°E., 35 lks. dist. mkd. T20S R12W S13 BT.
A Spruce 14" dia., bears S.45°W., 25 lks. dist. mkd. T20S R12W S14 BT.
A Spruce 8" dia., bears N.30°W., 25 lks. dist. mkd. T20S R12W S11 BT.

Survey by W.G. Corbitt; B. Senn; Paul Krugur; N. Seethoff - For: Crown Zellerbach - March 29, 1943 - C.S. File 52/91

Set 1½" I.Pipe in place of old rotten post mkd. by Frey, 1936, and in it set 2"x2"x5 ft. Spruce post, from which
Orig. Spruce now 18", S.43°30'W., to nail, 11.3 ft., scribed "S14 T20R12W".
Orig. Spruce now 14" snag, N.46°30'E., 9.9 ft. to nail scribed "S12T20R12W".
Orig. Spruce now 48", S.59°E., 15.5 ft. slope 51%=13.8 ft. to nail. Blazed face covered with overgrowth.
Corner stands on NW. slope about 80 ft. East of gulch.

Survey by G.R. Lecklider - For: Mrs. M.A. Patrick - Feb. 1958 - M 8-38

(Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Found - 16" Spruce, N.60°E., 4.6 ft.
(Other BTs destroyed by logging.)
Set 4 x 4 post, from which
30" Spruce, East 23.0 ft.
30" Hemlock, N.12°E., 36.0 ft.

Stuntzner Engineering & Forestry - For: Western Pacific
Timber Survey - November 15, 1992 - M 116-32

Found - 1½" O.D. iron pipe.
24" rotten Spruce stump, tag on ground next to it,
bears N.74°E. 17.0 ft. (no record).
18" rotten Hemlock stump, tag, bears S.69°E. 12.8
ft. (no record).
9" Fir, tag, bears S.83°W. 9.3 ft. (no record).
Bearing Object, iron fence post, 4 ft. high bears
S.03°E. 1.85 ft. (no record).
New BTs- 11" Fir with "X" chop at breast height, tag, bears
N.15°W. 11.35 ft.
Set - 3/4" x 30" iron rod with 2" alum. cap marked:
T20S R12W
S11 12
S14 13
1992
LS 1342

Set along side of iron pipe.

Found OK 8/94 by Stuntzner - M120-75 A-D; C.S. File 63/145.