

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 600542

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 12 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 23)

-----  
Set ¼ sec. post, from which  
A Fir 24" dia., bears N.87°E., 80 lks. dist.  
A Spruce 30" dia., bears N.65°W., 75 lks. dist.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #745, dated May 1, 1902 - (DCSO records Vol. 1 Page(s) 75)

-----  
Set a Spruce post 4 ft. long, 4" sq., 24" in the ground, marked ¼ S 11 on W. and 12 on E. faces, from which  
A Spruce 8" dia., bears N.82½°E., 16 lks. dist. mkd. ¼ S12 BT.  
An Alder 8" dia., bears N.38°W., 6 lks. dist. mkd. ¼ S11 BT.

Survey by G.R. Lecklider - For: Mrs. M.A. Patrick - Feb. 1958 - M 8-38

-----  
Found - Post, badly rotted.  
24" Spruce snag, N.82½°E., 10.6 ft.  
New BTs -5" Spruce N.10°W., 8.8 ft.  
4" Spruce S.60°W., 4.0 ft.

Fd. OK, Nov. 1992 by Stuntzner - M 116-32