

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 22)

Bank of lake. Set post corner of secs. 1, 2, 11 and 12, from which

- A Spruce 30" dia., bears N.50°W., 12 lks. dist.
- A Spruce 72" dia., bears S.45°E., 29 lks. dist.
- Alder 12" dia., bears N.60°E., 38 lks. dist.
- Spruce 8" dia., bears S.83°W., 60 lks. dist.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #745, dated May 1, 1902 - (DCSO records Vol. 1 Page(s) 69 and 73)

(Page 69)
I make search for but am unable to find any trace of the cor. of secs. 1, 2, 11 and 12. I set temp cor.

(Page 73)
The cor. of secs. 1, 2, 11 and 12 is gone and witness trees cut down; stumps standing. Reestablish the cor. from the old stumps by marking a Maple 8" dia., T20S S1 on the NE.; R12W S12 on the SE.; S11 on the SW.; and S2 on the NW. faces, also 5 notches on the S. and 1 notch on the E. angle of same; from which

- A Hemlock 8" dia., bears N.86°E., 35 lks. dist. mkd. T20S R12W S1 BT.
- A Maple 5" dia., bears S.43°E., 3 lks. dist. mkd. T20S R12W S12 BT.
- A Maple 8" dia., bears S.45°W., 3 lks. dist. mkd. T20S R12W S11 BT.
- A Spruce 7" dia., bears N.9°W., 49 lks. dist. mkd. T20S R12W S2 BT.

August 1, 1905

Survey by W.G. Corbitt; B. Senn; Paul Krugur; N. Seethoff - For: Crown Zellerbach - Oct. 23, 1941 - C.S. File 52/91

Found square Alder stake without marks, standing presumable for corner. To preserve position of this marker, right or wrong,

I set 1½" I.P. in ground where stake stood, from which bears 10" Maple S.30°E., 19.6 ft. scribed S12, rest rotted away. 32" Hemlock stump N.17°E., 15.5 ft. to 1½" pipe in center of the stump, 15.2 ft. to face of old blaze showing scribe marks / 1. Most of inscription has been destroyed when Hemlock was cut down. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

I left a 2"x2"x4 ft. Cedar post here. As there is a questionable set of notes given for this corner in the line run E. between 2 and 11, further info. should be obtained.

Fd. Aug. 1980 by P. Fox - M 84-71

Survey by G.R. Lecklider - For: Mrs. M.A. Patrick - Feb. 1958 - M 8-38

Found - 1½" Pipe for corner.
 Maple, S.30°E., 19.7 ft. from Crown Zellerbach 1941.

New Accessories:

- 10" power pole N.24°E., 25 ft.
- 10" Spruce, S.40°E., 40.8 ft.
- 20" Spruce S.5°E., 68.1 ft.
- 48" Spruce N.88°W., 132.2 ft.

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1077 - surveyed Sept. 1981/Oct 1982 - (DCSO records Vol. 44 Page(s) 17105-06)

The cor. of secs. 1, 2, 11 and 12, and meander cor. on shore of Siltcoos Lake, perpetuated and recorded by Corbitt in 1941, from original evidence, no longer in existence, subsequently perpetuated and recorded by Lecklider in 1958, monumented with an iron pipe, 2" dia., firmly set, projecting 1" above ground, from which the remains of bearing trees and a bearing object mkd. by Lecklider:

- A power pole 10" dia., bears N.24°E., 40 lks. dist. with scribe marks S1 RE 4079 BP visible.
- A Spruce snag 7" dia., bears S.41°E., 60 lks. dist. with scribe marks 12 E4 visible on open blaze.
- A sawed Spruce stump 18" dia., bears S.5°W., 105½ lks. dist. with scribe marks 79 BT visible on open double blaze.
- A Spruce 55" dia., bears N.86°W., 200 lks. dist. with incorrect scribe marks S11 RE 4079 visible on opened blaze.

At the corner point
 Set an alum. post 28" long 2½" dia., 24" in the ground, with alum. cap mkd:

T 20	S	R 12	W	
	S 2		S 1	
	S 11		S 12	MC
				1982

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. cor. for 1, 2, 11 and 12

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which new bearing trees
A Spruce 8" dia., bears S.7°E., 91 lks. dist. mkd. T20S R12W S12 BT.
A Spruce 7½" dia., bears S.4°W., 77½ lks. dist. mkd. T20S R12W S11 BT.
Deposit iron pipe alongside aluminum post.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Aug. 16, 1988 - C.S. File 62/59-1

Found - 1982 BLM ¾" alum. cap on a 2½" O.D. alum. pipe, protrudes 5" above ground.
A 1½" I.D. Iron pipe was found 5" below ground along West edge of alum. cap and pipe. This apparently is the position commonly accepted as the corner location.
10" dia. power pole # " Co84 4" with scribe marks "S1RE4079BP", bears N.24°E., 25.0 ft. (agrees w/rec)
10" now 6" dia., 5 ft. high rotted Spruce snag, no scribing visible bears S.41°E., 39.6 ft. (agrees w/ 1982 BLM record)
20" now 12" dia., 3 ft. high rotted Spruce stump, scribe marks visible "79 BT" bears S.5°W., 69.0 ft. (BLM rec. S.5°W., 69.9 ft.)
48" now 60" dia. Spruce with a partially healed single blaze, scribe marks visible "S11 RE4079" bears N.88°W., 132.2 ft. (agrees w/rec.)
8" now 14" dia. Spruce with a fully healed single blaze, bears S.7°E., 60.1 ft. (agrees w/rec)
7½" now 12" dia. Spruce with a partially healed single blaze, illegible scribe marks visible, bears S.4°W., 51.1 ft. (agrees w/rec.)
No original BTs or BTs from GLO 1905 resurvey found.
1½" I.D. Iron pipe firmly set an protruding 10" above ground, bears S.31 ¾°E., 19.7 ft. (Crown Zellerbach, 1941)
A loosely set 1½" I.D. Iron pipe protruding 11" above ground bears N.47°E., 51.7 ft. (Source unknown)
No new accessories.
Monument lies approx. 100 ft. South of South lake shore of Siltcoos Lake, near the first cove West of railroad bridge at mouth of Fiddle Creek Arm.

Stuntzner Engineering & Forestry - For: Western Pacific Timber Survey -November 15, 1992 - M 116-32

(Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

(Corner Report Only)

Found - 3½" alum. cap on 2" inside dia. alum. pipe per BLM.
74" Spruce, visible scribe in rotten face, tag,
bears N.88°W. 130.73 ft.
14" rotten Spruce stump, visible scribe, tag, bears
S.05°W. 69.04 ft. (M8-38, S05°E. 68.1 ft.).
15" Spruce with healed face, tag, bears S.04°W.
50.66 ft.
16" Spruce with healed face, tag, bears S.07°E. 59.6
ft.
A stump that is possible remnants of a 10" Spruce,
now 6" stub, bears S.40°E. 40.81 ft.
1½" inside dia. iron pipe bears S.30°E. 19.7 ft.
Power pole, visible scribe "S1 RE 4079 BP", bears
N.24°E. 25.0 ft.

Found OK by Manseth, Nov. 1993 - M 124-21
Fd. OK - Robert Ward - 6/3/96 - M 125-12
Found OK by Manseth, 4/1998 - M 129-1 A&B
Fd. OK by Hostetter, Sept. 1999 - M133-40