

PRIMARY CORNER DESCRIPTION Cor. Secs. 30 & 31 T20-11 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 150

Set a post, 4½ ft. long, 4" sq., 24" in the ground marked S30 on N., CC T20S R11W on E., S31 on S. faces, with 1 notch on S. and 5 notches on N.faces; from which

An Alder 15" dia., bears N.55½°E., 24 lks. dist. mkd: T20S R11W S30 BT.

A Fir 15" dia., bears S.66°E., 4 lks. dist. mkd: T20S R11W S31 BT.

A Fir 18" dia., bears N.25°W., 18 lks. dist. mkd: T20S R11W S30 & S31 BT.

Troy J. Rambo - For: Port Blakely Tree Farms - Oct. 1998 - M 131-9

Found - 20" D.Fir stump with visible scribes (orig.) bears N.25°W., 18 lks.

Set - 5/8" x 30" rebar with a 2" alum. cap, from which:
12" Hemlock (twin) bears N.24°W., 24.9 ft., scribed "T20S R11W CC BT"

21" Spruce bears N.23°E., 23.9 ft., scribed "T20S R11W S30 CC BT"

R11W 20" D.Fir bears S.46°E., 35.2 ft., scribed "T20S S31 CC BT"

10" D.Fir bears S1°E., 35.5 ft., scribed "T20S R11W S31 CC BT"

Note - All BT faces painted red, distances measured to a 6" spike at side center base. Bearings were measured with a hand compass (mag. delc. 20°E.) and a 6 ft. steel fence post was set within 2 ft.