

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25 only (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 9)

Set post corner of secs. 19, 24, 25 and 30; from which
A Spruce 3" dia., bears S.25°W., 70 lks. dist.
A Spruce 24" dia., bears S.35°E., 58 lks. dist.
A Spruce 40' dia., bears N.15°E., 38 lks. dist.
A Spruce 36" dia., bears N.48°W., 35 lks. dist.

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 153)

Intersect West bdy. of Tp. 3.40 chs. S. of Cor. to secs. 19, 30, 25 and 24, which is a decayed post, 4" sq., mkd. T20S S19 on NE.; R11W S30 on SE.; R12W S25 on SW.; S24 on NW. face, with 2 notches on S. and 4 notches on N. edges; from which
A Spruce 40" dia., bears N.15°E., 38 lks. dist. mkd. T20S R11W S19 BT.
A Spruce 24" dia., bears S.35°E., 58 lks. dist. mkd. T20S R11W S30 BT.
A Spruce 3" dia., bears S.25°W., 70 lks. dist. mkd. T20S R12W S25 BT.
A Spruce 36" dia., bears N.48°W., 35 lks. dist. mkd. T20S R12W S24 BT.

Survey by Warren D. Hootman - For: Crown Zellerbach Corp. - Jan. 30, 1963 - C.S. File 51/249-1 and M 22-36

The corner is witnessed by the stumps of the original Spruce trees to the East which were:
40" Spruce N.15°E., 25.08 ft.
24" Spruce S.35°E., 38.28 ft.
I set a new corner with a 1" pipe, brass cap
Corner lays 40 ft. East of a small creek and 37 ft. South of a logging road up the S. side of Perkins Creek.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - June 9, 1992 - C.S. File 64/26-15

Found - 3" dia., brass cap on a 1¼" O.D. Iron pipe protruding 12" above ground.
24" now 60" dia., 8 ft. high Spruce stump, no blazes or scribing found, bears S.38°E., 40.8 ft. (Rec. S.35°E., 38.3 ft.) Orig. BT.

(Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec cor for 24 & 25 only (East)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

40" now 56" dia. 7 ft. high Spruce stump, with an axed "X" facing BC/IP and scribing found, illegible scribe marks and a "W" found facing S.70°W., on a previously opened blaze, bears N.15°E., 25.1 ft. (agrees w/rec.) Orig. BT.
3" now 10" dia. down and rotted Spruce, no blazes or scribing found, roots bears S.25°W., 46.2 ft. (agrees w/rec.) Orig. BT.
Unrecorded 28" dia. R.Cedar with a healed blaze, bears S.20°E., 15.6 ft. (tag dted 1968, N.20°W., 15.0 ft.)
New BTs -14" dia. R.Cedar, double blazed and scribed "T20S R12W S24 CS BT" bears N.46°W., 2.8 ft.
21" dia. Hemlock, double blazed and scribed "T20S R12W S25 CS BT" bears S.52°W., 43.5 ft.

Fd. ok by Troy J. Rambo - Oct. 1998 - M 131-9.

8/28/2002 - Per phone conversation with Brent Bacon, Menasha. This corner will be destroyed within the next couple of weeks, they will reference the corner. The approx. date for the corner to be replaced by is Dec.

Brent Bacon, Menasha Forest Products Corp. - Doyce Rose - 11/22/2002 - C.S. file 65/44-27

Found - 1" iron pipe with 3" brass cap marked "T20 S24 S25 S19 R12 R11 399" set over ½" iron pipe.
74" rotten spruce stump, S.38°E., 38.7 ft.
32" Cedar S.20°E., 15.1 ft. to side center, healed face.
24" Hemlock, S.51°W. 42.6 ft. to side center visible scribe (rec. 43.5 ft.)
15" Cedar now N.44°W. 2.2 ft. to side center leaning from logging (rec. N.46°W. 2.8 ft) visible scribe
New - Referenced monument with a Nikon DTM 530 Total Station and removed for logging operation. Reset above 1" iron pipe with 3" brass cap marked "T20 S24 S25 S19 R12 R11 399" with the above accessories remaining.
Note - The rotten spruce stump bearing N.15°E., 25.1 ft. was destroyed by a spur road. The corner falls just south of this spur road.