

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T21-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 787)

Set post cor. of secs. 7, 12, 13 and 18, from which
A Fir 36" dia., bears S.25°W., 34 lks. dist.
A Hemlock 7" dia., bears S.13°E., 23 lks. dist.
A Hemlock 18" dia., bears N.46°W., 59 lks. dist.
A Hemlock 8" dia., bears N.68°E., 46 lks. dist.

O.F. Thiel - For: Chas. Turpin - Aug. 27, 1908(?) - Field Book 115 Page 146-A

Yew post. All trace of old trees gone. Marked;
Fir 20" S.88½°W., 135 lks.
Maple 20" S.35°E., 43 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - Jan. 5, 1962 - C.S. File 49/89-46

Found scribed stake on creek bank scribing found "T" 1S R4W S S". Found rotten Fir stump West 91.2 ft scribed "BT", scribing looks like Thiel's. No trace found of any original BTs. Calls in govt. field notes fit creek crossings North and South from cor., but do not fit creek crossing East of cor., very doubtful if cor found is in right location.

Douglas Co. Surveyor Office - Milo E. Godfrey - Nov. 5, 1964 - C.S. File 49/68

Found scribed wooden stake and old stump scribed "BT" approx. 100 ft. West of stake. No orig. BTs. No record of renewal.

BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15015-16)

The Sec. Cor., monumented with a Cedar post 4 x 4 ins., 18" long, 12" in the ground, with fragmentary scribe marks visible on W. face. This position has long been recognized as the cor. by adjacent land owners, and is accepted as the best existing evidence of the position of the original cor., from which bearing trees mkd. by person(s) unknown:

A sawed Cedar stump 30" dia., bears S.10°E., 96 lks. dist., with axe marks visible on double blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T21-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A sawed Fir stump 20" dia., bears S.88°W., 137 lks. dist., with scribe marks BT visible on opened blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 21 S
R 5 W R 4 W
S 12 | S 7
S 13 | S 18
1971
from which new bearing trees:
A Fir 15" dia., bears N.69°E., 76 lks. dist. mkd. T21S R4W S7 BT.
A Fir 21" dia., bears S.84°E., 69 lks. dist. mkd. T21S R4W S18 BT.
A Fir 6" dia., bears S.60°W., 270 lks. dist. mkd. T21S R5W S13 BT.
A Fir 6" dia., bears N.36°W., 53 lks. dist. mkd. T21S R5W S12 BT.
Deposit Cedar post alongside iron post.

Fd. OK, Nov. 1986 by Wm. Guile - M 103-9
Fd. OK, Dec. 1991 by D. Peel - M 114-41

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20418-9)

The cor. of secs. 7, 12, 13 & 18, monumented with an iron post, 2 1/2" diam., firmly set, projecting 2" above ground, with properly marked brass cap,
from which the remains of BTs mkd. by Peterson and Berry
A fir, 21" diam., bears N.70 1/4°E., 76 lks., with healed blaze. (Record, N.69°E.)
A sawed fir stump, 27" diam., bears S.84°E., 69 lks., with healed blaze.
A fir, 20" diam., bears S.60 1/2°W., 270 lks., with healed blaze. (Record, S.60°W.)
and new bearing trees
A cedar, 17" diam., bears S. 47 1/2°E., 90 lks., mkd. T21S R4W S18 BT.
A fir, 24" diam., bears N.57°W., 107 lks., mkd. T21S R5W S12 BT.
The cor. is located W., 0.30 chs. from Pheasant Creek, 10 lks. wide, course S. 30°W.

2