

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 777)

-----  
Set post cor. of secs. 17, 18, 19 and 20, from which  
A Fir 60" dia., bears S.20°W., 58 lks. dist.  
A Fir 10" dia., bears S.13°E., 106 lks. dist.  
A Fir 15" dia., bears N.65°E., 15 lks. dist.  
A Fir 18" dia., bears N.15°W., 55 lks. dist.

Oscar Thiel - For: Elva Littlepage - Dec. 1943 - Field Book 117 Pg. 104

-----  
All old trees gone, stumps of 3 trees found. Set an iron shaft 3/4" x 30" in ground.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - March 10, 1958 - C.S. File 49/68-2

-----  
Found - 3/4" shaft at corner set by Thiel, 1943.  
Also find stump hole and parts of rotted Fir that checks bearing and dist. for orig. NW. BT.  
Find base of old stump that checks orig. SW. BT.  
I do not set brass cap at corner.  
New BTs- 6" R.Fir bears S.65°E., 17.8 ft. scribed S20 T21S R4W CS BT.  
10" R.Fir bears N.84°E., 27.0 ft. scribed S17 T21S R4W CS BT.  
18" double Laurel N.71°W., 119.0 ft. scribed S18 T21S R4W CS BT.  
No trees near in SW.

Fd. OK, DCSO by M. Godfrey, Oct. 9, 1964 CS File 49/68-10

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 1968 - C.S. File 54/14-40

-----  
Found - 3/4" shaft at fence corner & BTs as recorded in 1958  
6" now 15" R.Fir, alive, S.65°E., 17.8ft., healed blaze.  
10" now 18" R.Fir, alive, N.84°E., 27.0 ft., rescribed "T21S R4W S17 CS BT" over old scar.  
18" now 24" double Laurel, alive, N.71°W., 119.0 ft., scribe marks visible on nearly healed blaze.  
(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set Brass cap at cor. mkd: County Surveyors Office  
T 21 S R 4 W  
S 18 | S 17  
S 19 | S 20  
1968  
New BT - 10" D.Fir S.44°W., 52.0 ft. mkd. T21S R4W S19 CS BT  
Reset shaft alongside brass cap, fences N., S. and E-W.

Fd. and used in BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15023)

Charles W. Guile - For: Weyerhaeuser Co. - Nov. 17, 1986 - C.S. File 63/45(n) and M 103-9  
-----  
Found - DCSO 1968 brass cap.  
22" Fir bears N.82 3/4°E., 26.9 ft.  
30" Fir bears S.66½°E., 17.9 ft.  
22" Fir bears S.42½°W., 51.9 ft.  
New BT - 16" Fir bears N.72¼°W., 10.7 ft. to "W" nail, "SE Cor. S18 BT".

Fd. and used in BLM Resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson; Garry L. Moore, Cadastral Surveyors and Garry L. Moore, Surveying Technician - Under Group #1406, Surveyed Feb. 2, 1988/Jan. 6, 1989 - (DCSO records Vol. 48 Page(s) 18608-09)