

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 770)

Set ¼ sec. post, from which
A Fir 8" dia., bears S.52°E., 121 lks. dist.
A W.Oak 6" dia., bears S.48°W., 70 lks. dist.

Chas. C. Bayles - July 1953 - C.S. File 41/183

No trace of corner or original BTs. Set Fir post.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Nov. 1964 - C.S. File 49/68-28

Found - Fir stake set by Bayles in 1953, and red painted broom handles North and East of corner.
No trace of original BTs.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 4 W
¼ S20 | S21
1964

New BTs- 12" D.Fir N.15°W., 7.0 ft. mkd. ¼ S20 CS BT.
18" D.Fir S.39°E., 36.0 ft. mkd. ¼ S21 CS BT.

Fd. OK, Oct. 1981 by W. Eimstad - M 89-25
Fd. OK by L. Roberts, March 2000 - M134-42

Ron Rice - For: Weyerhaeuser Co. & Beckley Timber LLC - 6/2016 - M172-21

Condition report
Found - Co. Surveyors brass cap dated 1964
26" D.Fir bears N.15°W., 7.0', healed face.
42" D.Fir bears S.39°E., 36.0', healed face.
Steel post adjacent to corner.

Fd. BC & 2 BTs 5/2018 by A DeGroot - M171-41