

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 33

Alias	Description

David Wellman - For: Summerwood Inc. - June 1999 - M 132-12	

Set - 2½" O.D. x 36" iron pipe with 2½" brass cap 0.7 ft above ground stamped:	T21S R4W C ¼ S33 PLS 2163 1999
12" Fir N.55 3/4°E., 37.9 ft. to spike set side center scribed "C¼ S33 BT"	
10" Fir S.42½°E., 18.0 ft. to spike set side center scribed "C¼ S33 BT"	
12" Fir S.69°W., 16.3 ft. to spike set side center scribed "C¼ S33 BT"	
12" Fir N.23°W., 21.4 ft. to spike set side center scribed "C¼ S33 BT"	
Ken Hoffine, Lone Rock Timber Management - Crew: Gary Angiolet & Ignacio Roman - 5/4/2017 - C.S. File 65/95-41	

Found - 1999 Wellman 2½" Iron pipe with 2½" brass cap offset as shown on sketch (brass cap is solidly cemented on iron pipe)	
14" D.Fir bears N.53¾°E., 37.9 ft. (rec. N.55¾°E., 37.9 ft.) healed face & tag.	
Rec. 10" D.Fir at S.42½°E., 18.0 ft. is down & uprooted.	
Rec. 12" D.Fir at S.69°W., 16.3 ft. is down & uprooted.	
Rec. 12" D.Fir at N.23°W., 21.4 ft. is down & uprooted.	
New - 18" D.Fir bears N.55½°W., 28.6 ft. we scribed C¼ S33 BT and tag Tree.	
5/8"x40" reference rod with orange plastic cap mkd LONE ROCK TIMBER PLS 2291 bears S.22°05'E., 18.69'	
5/8"x40" reference rod with orange plastic cap mkd LONE ROCK TIMBER PLS 2291 bears S.55°35'W., 15.23'	
Note - We ran a random transit traverse beginning at the center ¼ of section 33 easterly to the east ¼ of sec. 33. We then continued the traverse southerly to the south 1/16th corner between secs 33 & 34. We checked our traverse for closure with GPS control points we established at the center ¼ and at a road opening near the south 1/16 corner between sections 33 & 34. We marked property boundaries on true line between corners.	