

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T20-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 748)

Set $\frac{1}{4}$ sec. post, from which
A Redwood 12" dia., bears N.9°W., 42 lks. dist.
A Redwood 6" dia., bears S.16°W., 16 lks. dist.

Douglas Co. Surveyors Office - James Byron - March 1969 - C.S. File 54/14-31A

Looked for, not found.
Found old brush line running East and West. Plus, some old Cedar stumps cut in to but no trace of scribing or $\frac{1}{4}$ cor. (Note has been logged and burnt and new trees approx. 8" to 12" dia.) No trees match bearing and dist.

BLM Resurvey by Floyd Brooks; Gordon Popken; Gary Oviatt; Timothy Kent, Cadastral Surveyors, Under Group #724, Surveyed Aug. 1970 - (DCSO records Vol. 37 Page(s) 15279)

Point for the $\frac{1}{4}$ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:
T 20 S R 4 W
 $\frac{1}{4}$ $\frac{S\ 33}{S\ 4}$
T 21 S
1971

from which
A Fir 10" dia., bears S.9°W., 27 lks. dist. mkd. $\frac{1}{4}$ S4 BT
A Fir 12" dia., bears N.70°W., 20 $\frac{1}{2}$ lks. dist. mkd. $\frac{1}{4}$ S33 BT.

Fd. OK, April 1990 by Peel - M 110-2
Fd. OK, Jan. 1991 - M 111-62