

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 748)

Set post cor. of secs. 3, 4, 33 and 34, from which
A R.Fir 9" dia., bears N.8°W., 14 lks. dist.
A R.Fir 8" dia., bears N.74°E., 15 lks. dist.
A R.Fir 9" dia., bears S.26°E., 17 lks. dist.
A R.Fir 8" dia., bears S.30°W., 11 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
March 20, 1969 - C.S. File 54/14-35

REPORT ONLY

Found - Unrecorded 1/2" monel pipe for cor. and possible
OBTs.

9" now 22" Fir, stump, N.8°W., 9.2 ft., fragmentary
scribe, does not appear to be orig. Ring count
impossible due to decay.

8" now 20" Fir, stump, S.26°W., 7.1 ft., burned,
decayed and excessively chopped up. No scribe
found.

No trace of other O.B.Ts.

Weyerhaeuser reference trees as follows:

14" D.Fir S.50°E., 20 ft. tag ("W") nail, small
scar at base.

16" D.Fir N.72°W., 70.8 ft. tag, ("W") nail, small
scar at base.

This corner lies on moderate southerly slope.

BLM Resurvey by Floyd Brooks; Gordon Popken; Gary Oviatt;
Timothy Kent, Cadastral Surveyors, Under Group #724, Surveyed
Aug. 1970 - (DCSO records Vol. 37 Page(s) 15277-78)

The Sec. cor., perpetuated and recorded by Weyerhaeuser
Timber Co., in 1958, monumented with an iron pipe, 5/8" dia.,
firmly set, projecting 1" above ground, from which the
remains of the original bearing trees:

A decayed Fir stump 18" dia., bears N.2°E., 14 lks. dist.,
with scribe marks BT visible on open blaze. (Rec.
N.8°W.)

A sawed and decayed Fir stump 18" dia., bears S.28°W., 11
lks. dist., no marks visible. (Rec. S.30°W.)

and bearing trees mkd. by Weyerhaeuser Timber Co.

A Fir 12" dia., bears N.69½°E., 79 lks. dist., with a nail
with "W" embossed on the head, at base.

A Fir 17" dia., bears S.49°E., 30 lks. dist., with healed
lower blaze.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 15" dia., bears N.70 3/4°W., 107 lks. dist., with healed lower blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 20 S R 4 W
S 33 | S 34
S 4 | S 3
T 21 S
1971

from which new bearing trees

A Fir 6" dia., bears N.49½°E., 59 lks. dist., mkd. T20S R4W S34 BT.

A Fir 13" dia., bears S.19°W., 143½ lks. dist. mkd. T21S R4W S4 BT.

A Fir 9" dia., bears N.39½°W., 66 lks. dist., mkd. T20S R4W S33 BT.

Reset iron pipe alongside iron post.

Fd. OK, April 1990 by Peel - M 110-2

Fd. OK, Jan. 1991 by Peel - M 111-62

Lane Co. Surveyor's Office Mikeal Blomme' - Crew: Bruce Bothel & Stuart Duce - 12/28/2015 - C.S. File 65/111-49

Found - A 3¼" BLM brass cap (properly mkd) atop a 2½" iron post, 4" above grade.

1854 - The outline of a rotten Fir stump, flush w/ the surface brs S.27°50'W., 7.7' to CTR (S.30°W., 7.3').

1958 - A 20"x5' tall rotten Fir high-stump brs N.67°52'E., 52.2' to CTR (N.68°E., 52.2' to 'W' nail)

1958 - 39" D.Fir w/low healed face S.49°40'E., 20.1' to CTR (shown on map)

1958 - 30" D.Fir w/low healed face N.72°W., 70.8' to CTR (shown on map)

1971 - An 18"x4' tall rotten Fir high-stump w/healed face brs N.48°05'E., 38.9' to CTR (N.49¼°E., 38.9').

1971 - A 24"x4' tall rotted Fir high-stump w/ healed face brs S.17°37'W., 94.2' to CTR (S.19°W, 94.7')

1971 - 24" D.Fir w/healed face N.40°45'W., 43.3' to CTR (shown on map)

New - Set 5/8"x30" rebar w/2" alum cap "LCS0-RP2-2015" 4" deep N.44°30'00"E., 31.53'

Note - Distance shown is to an aluminum nail set at side/center of live trees.

Continued next page

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Basis of bearing: N.72°W, from the brass cap to 1958 NW BT
Geographic map location: not of survey grade accuracy NAD
83/91 values: LAT: N 43°46'46.6" LONG: W 123°10'02.1"
Equipment used: LEICA TCR 1203 & SPECTRA PRECISION RANGER
DATA COLLECTOR.

BLM Dependent resurvey by Joseph M Mannix, Cadastral Surveyor
under Group No. 2921, surveyed May 2018/Feb. 2019 - (DCSO
records Vol. 59 Page(s) 24094)

The cor. of secs. 3, 4, 33, and 34, on the N. bdy. of the
Tp., reported by Mannix in 2017-18, monumented with an iron
post, 2½" dia., firmly set, projecting 2" above ground, with
a brass cap mkd. and accessories as described in the official
record of the resurvey by Mannix in 2021.