

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 760)

-----  
Set ¼ sec. post, from which  
A Fir 40" dia., bears S.88°E., 56 lks. dist.  
A Cedar 36" dia., bears N.7°W., 126 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Nov. 20, 1968 - C.S. File 54/14-34

-----  
Old fence cor. No O.B.T.s found. Logged and burned years ago.

Survey by Donald Peel - For: Weyerhaeuser Co. - Oct. 1990 -  
M 110-72

-----  
Set 2" x 42" iron pipe with brass cap & 6 ft. steel fence post 1 ft. South, from which  
16" Alder N.63½°E., 22.8 ft., bark scribed "¼ S14 BT"  
13" Alder S.66 ¾°E., 31.2 ft., bark scribed "¼ S14 BT"  
60" Fir stump, S.73½°W., 41.0 ft. scribed "¼ S15 BT"  
12" Cedar, N.51 ¾°W., 34.2 ft., scribed "¼ S15 BT"  
1/2" Rebar of unknown origin found near ¼ corner, bears S.01°41'30"W., 34.55 ft.

Found OK by D. Crowe, Nov. 2002 - M141-38

Edward Brown - For: Fruit Growers Supply Co. - 9/2023 -  
M182-67

-----  
Found - 2" brass cap iron pipe.  
Also fd a 1/2" rebar without cap as shown in M64-17  
S.03°30'06"W., 34.60' from iron pipe and brass cap.  
18" Alder, N.63°E., 22.8' to nail in face  
16" Alder, S.66°E., 31.2' to nail in face  
60" Fir stump, S.7°W., 41.0' to nail in face  
22" Cedar, N.51°W., 34.2' to nail in face  
Metal "T" post bears south, 1.0'.