

Alias	Description
Alias	Description
Alias	Description
Alias	Description

**ON COUNTY LINE BE SURE TO CHECK WITH
LANE CO. SURVEYORS OFFICE**

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 747)

Set ¼ sec. post, from which
A R.Fir 12" dia., bears N.10°E., 42 lks. dist.
A Redwood 12" dia., bears S.29°E., 30 lks. dist.

Weyerhaeuser Company by Glen McChesney - Nov. 1959 - C.S. File 53/104-1

Found - No trace of 1854 post.
12" Fir N.10°E., 42 lks. 27.7 ft., stump hole.
12" Redwood S.29°E., 30 lks., 19.8 ft., decayed wood, Cedar.

(Survey record, Lane Co. Aug. 1900) Old post gone. Found stump of 12" Red Fir. When mkd. bearing N.10°E., 43 lks., showing old face. Also fallen trunk of old "Redwood" Cedar 12", S.29°E., 30 lks.)

Set post from which:
8" Fir N.17½°W., 38 lks. 25.8 ft. Found 17" standing Fir with 2 faces. Chopped out upper face, found scribed "S 33¼ CS" The "33" in error, should have been "35".
4" Fir S.30°E., 29 lks., 19.1 ft., now 21" stump, chopped out and found "BT". Found long butt and chopped out negative "S2".

Set Iron pipe and Cedar post, set by dist. and brg. from 1900 County Surveyor's BTs.

New BTs- 17" Fir N.17°W., 24.4 ft., orig. BT, added "W" nail and plate.
10" Fir S.36°E., 39.6 ft., add "W" nails & plate.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 12, 1967 - C.S. File 54/14-32

Found - 1½" Iron pipe.
Orig. 17" Fir, now snag, N.17°W. 24.4 ft. scribe vis., same BT called for in 1900 reestablishment.
Orig. 10" Fir, face down, S.36°E., 39.6 ft. "W" BT.
Orig. 21" Fir stump, in place, decaying S.30°E., 19.1 ft., no scribe found.

New BTs- 13" D.Fir N.4°W., 30.0 ft. mkd. ¼ S35 DCS BT.
4" D.Fir S.53°W., 9.4 ft. mkd. ¼ S2 DCS BT.
Corner lies 90 ft. E. of old road on Lane-Douglas Co. line.

(Cont. Next Page)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Floyd Brooks; Gordon Popken; Gary Oviatt; Timothy Kent, Cadastral Surveyors, Under Group #724, Surveyed Aug. 1970 - (DCSO records Vol. 37 Page(s) 15275-76)

 The ¼ sec. cor., perpetuated and recorded by McChesney in 1959, monumented with an iron pipe, 2" dia., firmly set, projecting 12" above ground, from which the remains of the original bearing trees:

A sawed Fir stump 27" dia., bears S.29°E., 30 lks. dist., no marks visible.

and the remains of a bearing tree mkd. by Collier in 1900:

A Fir snag 17" dia., bears N.17½°W., 38 lks. dist., with scribe marks S 35 B visible on opened blaze.

and the remains of a bearing tree mkd. by McChesney:

A root hole bears S.36°E., 60 lks. dist., with a down Fir alongside 12" dia., no marks visible.

and bearing trees mkd. by Tracy in 1967:

A Fir 21" dia., bears N.4°W., 45½ lks. dist. with partially healed double blaze.

A Fir 6" dia., bears S.53°W., 14 lks. dist., with partially healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 20 S R 4 W
 ¼ S 35
 S 2
 T 21 S
 1971

from which a new bearing tree;

A Fir 13" dia., bears N.56°W., 78½ lks. dist. mkd. ¼ S35 BT.

Reset iron pipe alongside iron post.

Fd. Cor. OK, Feb. 27, 1987 by C. Guile - M 103-68
 Fd. OK, Oct. 1994 - M 120-70
 Fd. OK, Oct. 1997 - C.S. 65/15-18 - Kirk Adkin

BLM dependent resurvey by Craig L. Wanless & Daniel N. Patterson, Cadastral Surveyors, under Group #1577, Surveyed April 1991/April 1993 - Filed Jan. 12, 2004 DCSO - C.S. File 65/49-8 A-I

 The ¼ sec. cor. of secs. 2 & 35, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground with brass cap (properly) mkd.

from which the remains of BTs mkd. by Collier, Lane Co. Surveyor, in 1900, and reported by Brooks, Popken, Ovaitt, & Kent

continued next page

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; & 35, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed & decayed fir stump, 24" dia., bears S.29°E., 30 lks., no marks visible.
A fir snag, 20" dia., bears N.15°W., 38 lks. with scribe marks S35 ¼ visible on opened blaze. (Rec. N.17½°W.) and BTs mkd. by Tracy in 1967, and reported by Brooks, Popken, Ovaitt, & Kent
A fir, 15" dia. bears S.53°W., 14 lks., with healed blaze.
A fir, 21" dia. bears N.2°W., 45½ lks. with healed blaze, (Rec. N.4°W.)
and a BT mkd. by Brooks, Popken, Ovaitt, & Kent
A Fir 19" dia., bears N.56°W., 77½ lks., with healed blaze. (Rec. N.56°W., 78½ lks.)