

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

(THIS CORNER LIES IN LANE COUNTY - CHECK WITH THEIR OFFICE FOR ANY POSSIBLE INFORMATION NOT FILED WITH DOUGLAS COUNTY)

GL0 Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 747)

-----  
Set post cor. of secs. 1, 2, 35 and 36, from which  
A R.Fir 20" dia., bears S.14°W., 50 lks. dist.  
A Fir 30" dia., bears N.55°E., 90 lks. dist.  
A Redwood 40" dia., bears S.20°E., 55 lks. dist.  
A Redwood 6" dia., bears N.25°W., 82 lks. dist.

A.D. Collier, Lane Co. Deputy - June 4, 1912 - C.S. file 53/1

-----  
Found - 20" Fir S.14°W., 50 lks., standing OK.  
Also, the Redwood Cedar 40", S.20°E., 53 lks.  
Found stump of Fir 30", N.55°E., 90 lks.  
Other Fir gone.  
Set post CS and new BTs  
Fir 6", N.56°E., 9 lks.  
6" Fir, North 17 lks. "CS BT".

BLM Resurvey by Floyd Brooks; Gordon Popken; Gary Oviatt; Timothy Kent, Cadastral Surveyors, Under Group #724, Surveyed Aug. 1970 - (DCSO records Vol. 37 Page(s) 15274-75)

-----  
The Sec. cor., perpetuated by person(s) unknown, monumented with an unmarked sandstone, 15 x 9 x 8 ins., firmly set 10" in the ground, from which the remains of the original bearing trees:

A sawed Fir stump 33" dia., bears S.14°W., 50 lks. dist., no marks visible.  
A Cedar snag 12" dia., bears N.25°W., 82 lks. dist., with healed blaze.  
and a bearing tree mkd. by Collier in 1912:  
A Fir 20" dia., bears N.56°E., 9 lks. dist., with healed double blaze.  
and bearing trees mkd. by Weyerhaeuser Timber Co. in 1958:  
A Fir 15" dia., bears S.46½°E., 28½ lks. dist., with a nail with "W" embossed on the head, at base.  
A sawed Fir stump 33" dia., bears S.5½°W., 50 lks. dist., with a nail with "W" embossed on the head, at base.  
A Fir 45" dia., bears N.42½°W., 47 lks. dist., with a nail with "W" embossed on the head, at base.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 20 S R 4 W  
S 35 | S 36  
S 2 | S 1  
T 21 S  
1971

from which new bearing trees:

A Cedar 10" dia., bears N.21°E., 25 lks. dist., mkd. T20S R4W S36 BT.

A Fir 12" dia., bears S.19½°E., 28 lks. dist., mkd. T21S R4W S1 BT.

Deposit corner stone alongside iron post.

Corner is located adjacent to cor. of wire fences extending S. and W.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Nov. 4, 1991 - C.S. File 64/21-4

Found - ¾" BLM brass cap on a 2½" O.D. Iron pipe protruding 4" above ground.

A firmly set sandstone rock is found along East edge of BC/IP, top measures 8" x 4", protrudes 4" above ground. Unknown origin.

20" now 33" dia. 1½ ft. high D.Fir stump, no marks visible, bears S.12½°W., 33.0 ft. (Rec. S.14°W., 33.0 ft.) Orig. BT.

6" now 8" dia. 3½ ft. high burnt Cedar stub, no marks visible, bears N.28½°W., 54.1 ft. (Rec. N.25°W., 54.1 ft.) Orig. BT.

6" now 25" D.Fir with a fully healed double blaze, bears N.56°E., 5.9 ft. (agrees w/rec)

22" dia., 1½ ft. high D.Fir stump with a fully healed lower blaze, bears S.52°E., 18.8 ft. (Rec. S.46½°E., 18.8 ft.)

33" dia. 2½ ft. high D.Fir stump with a rotted blaze, no scribing visible, bears S.2½°W., 32.5 ft. (Rec. S.5½°W., 33.0 ft.) 1958

45" dia. 5 ft. high D.Fir stump with a fully healed single blaze, bears N.45½°W., 31.0 ft. (Rec. N.42½°W., 31.0 ft.) 1958

10" now 14" dia. I.Cedar with a fully healed single blaze, bears N.16°E., 16.5 ft. (Rec. N.21°E., 16.5 ft.) 1971 BLM

12" now 20" dia. W.Fir with a fully healed single blaze, bears S.23½°E., 18.5 ft. (Rec. S.19½°E., 18.5 ft.) 1971 BLM

New BT - 6" dia. D.Fir, double blazed and scribed "T20S R4W S35 CS BT" bears N.58°W., 15.0 ft.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner is approx. 150 ft. West of a BLM gravel road. All bearings taken away from corner. Wire fence affects compass bearings.

BLM Dependent resurvey by Joseph M Mannix, Cadastral Surveyor under Group No. 2921, surveyed May 2018/Feb. 2019 - (DCSO records Vol. 59 Page(s) 24093-4)

-----  
The cor. of secs. 1, 2, 35, and 36, on the N. bdy. of the Tp., reported by Brooks et al., in 1970-71; perpetuated by Smith, in 1991; monumented with an iron post 2½" dia, firmly set, projecting 4" above ground, (alongside of which is a sandstone, 8x4", firmly set, projecting, 4" above the ground, with no marks visible) with a brass cap (properly) mkd. from which the remains of the bearing trees reported by Brooks et al.

A cedar, 20" dia., bears N.21°E., 16.5 ft., with a healed blaze.

A fir, 27" dia., bears N.56°E., 5.9 ft., with a healed blaze.

A decayed fir stump, size indeterminate, bears S.46½°E., 18.8 ft., with a healed blaze.

A fir, 30" dia., bears S.19½°E., 18.5 ft., with a healed blaze.

A decayed fir stump, size indeterminate, bears S.5½°W., 33.0 ft., no marks visible.

A fir stump, 40" dia., bears N.42½°W. 31.0 ft., with a healed blaze.

and a bearing tree mkd. by Smith

A fir, 12" dia., bears N.53¼°W., 14.7 ft., with a healed blaze.

No new bearing trees available in sec. 2. Corner is located alongside a fence cor., with wire fence extending S. and W.