

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 037010

PRIMARY CORNER DESCRIPTION NE Cor. Elijah Estes DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated June 8, 1857 - DLC Volume, Page 6

Set post NE. Cor. CL. #37, from which
A Fir 40" dia., bears S.2°W., 612 lks.
A Fir 40" dia., bears S.80°E., 63 lks.

Douglas Co. Surveyors Office - B.B. Irving; N.E. Richardson
April 23, 1941 - C.S. File 53/87

Location identified from the stump of original bearing tree
which I chopped out and found the BT scribe marks in good
condition:
40" Fir S.80°E., 63 lks.
Orig. BT, 40" Fir S.2°W., 612 lks. in good shape, bark
blazed and has been remarked.
For the Corner: blazed and rescribed a Fir 30" dia. at the
corner of property fence.

Douglas Co. Surveyors Office - Milo Godfrey, Deputy - Stoffel
and Stone, crew - Dec. 1964 - C.S. File 49/68-54

Found - 40" D.Fir mkd. by Irving in 1941 for corner. (Bark
scribing visible, "B" and "S".)
Old rotten Fir stump S.80°E., 41.6 ft., no marks
visible.
70" Fir stump S.2°W., 404 ft., old flattened area on
bark, but no scribing.
Set WITNESS CORNER 10 ft. North of corner. Brass cap mkd.
"County Surveyors Office 1964 T21S R5W W.C. N.E. DLC 37 10
ft. S. to corner".
New BTs- 12" W.Oak S.42°E., 26.0 ft. mkd. WC NE DLC 37 CS BT.
25" W.Oak N.48°W., 94.0 ft. mkd. WC NE DLC 37 CS BT.
Corner tree is in fence corner, fences South and West.

Douglas Co. Surveyors Office - Karen Reed; Stephen Flause,
crew - Oct. 23, 1979 - C.S. File 60/34-22

Found - Orig. 40" Fir now a 30" dia. 4 ft. stump, badly
rotted, bears S.80°E., 41.6 ft.
12" W.Oak now 9" with healed double blaze, bears
S.42°E., 26.0 ft. (W.C. tree from 1964)
25" Oak now a 25" dead snag with well healed double
blaze, bears N.48°W., 94.0 ft. (W.C. tree from
1964)
An orig. 40" dia. Fir now a 70" dia. stump, bears
S.2°W., 404.0 ft. No scribing found.
(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 037010

PRIMARY CORNER DESCRIPTION NE Cor. Elijah Estes DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set a 1" x 36" I. Pipe with brass cap stamped "Douglas County Surveyor W.C. T21S R5W 10 ft. S. to Cor. NE. DLC 37 1979". Set at proper bearing and distance from W.C. BTs. and corner tree.
New BT - 15" D.Fir bears N.51½°E., 85.0 ft. scribed "WC NE DLC 37 CS BT" in double blaze. (87.2 ft. at 13°)
Tagged tree facing corner and road.
Corner tree is in fence corner. Fence course S-W. New tags on corner tree and NW. BT from 1964.
Found - A 30" Fir now 46" with partial bark scribe "B S" rescribed by Irving, 1941 for corner tree. No brass cap set by Godfrey.

30" Irving corner tree FD. OK by W. Haines - M 92-30

Found OK by Les Roberts, April 2000 - M134-66

Fd. & used on BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20398)