

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32, T20-5

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 785-86)

Set post cor. of secs. 5, 6, 31 and 32, from which

- A R.Fir 70" dia., bears N.18°E., 26 lks. dist.
- A Cedar 30" dia., bears S.7°E., 32 lks. dist.
- A Cedar 15" dia., bears N.68°W., 8 lks. dist.
- A Hemlock 24" dia., bears S.60°W., 95 lks. dist.

Fd. and used in GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 832-33)

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - April 1962 - C.S. File 49/89-51

Found - Dead Fir snag, now 66", N.18°E., 17.1 ft., previously opened, scribing visible on old face "S & W" and portions of other letters.

- 42" R.Cedar N.68°W., 5.3 ft., center dead, no scribing visible.
- Cedar S.70°E., 21.1 ft. is uprooted and down, impossible to fix exact location where it stood.

Did not find SW. tree.

Set Brass cap at cor. mkd: County Surveyors Office

S 31		S 32	T20S	
S 6		S 5	T21S	R5W
1962				

New BTs- 42" Cedar, N.68°W., 5.3 ft. mkd. T20S R5W S31 CS BT, rescribed.

- 6" Hemlock N.10°E., 20.6 ft. mkd. T20S R5W S32 CSBT
- 38" R.Cedar S.53°W., 87.6 ft. mkd. T21S R5W S6 CS BT

No suitable trees near in section 5.

BLM Resurvey by Floyd A. Brooks and Timothy A. Kent, Cadastral Surveyors, under Group #648, Surveyed Aug. 1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15264-65)

The Sec. Cor., remonumented by Godfrey in 1962, with an iron post, 1" dia., firmly set, projecting 14" above ground, with brass cap mkd. in 1962, from which the remains of the original bearing trees:

- A Fir snag 61" dia., bears N.18°E., 28 lks. dist., with scribe marks S R5W visible on opened blaze. (Rec. 26 lks.)

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32, T20-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Cedar snag 32" dia., bears S.7°E., 32 lks. dist., with healed blaze.

A root hole bears S.60°W., 95 lks. dist., with a down an decayed Hemlock alongside, 18" dia., no marks visible.

A Cedar 40" dia., bears N.68°W., 10 lks. dist., no marks visible on weathered face of blaze. (Rec. 8 lks.) This tree was remarked by Godfrey in 1962; scribe marks T20S R5W S31 CS BT visible on open double blaze.

and bearing trees mkd. by Godfrey:

A Hemlock 8" dia., bears N.9°E., 30 lks. dist., with fragmentary scribe marks visible on open double blaze.

A Cedar 45" dia., bears S.52°W., 133 lks. dist., with scribe marks T21S R5W S6 CS BT visible on open double blaze.

and a new bearing tree:

A Hemlock 12" dia., bears S.82½°E., 162 lks. dist., mkd. T21S R4W S5 BT.

Add marks BLM 1967 to brass cap.