

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 814)

Set ¼ sec. post, from which
A Fir 24" dia., bears N.51°W., 69 lks. dist.
A Cedar 12" dia., bears S.28°W., 24 lks. dist.

Wilford N. Haines, #239 - For: Woolley Logging Co. - Feb. 20, 1962 - M 23-34

Found - Scribed stake at fence corner.
I was at this corner about 1946. There was part of Cedar BT, S.28°W., 24 lks. There is a Fir stump N.51°W., 69 lks.
Set 1" x 1" x 36" T. Iron by stake.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Aug. 18, 1965 - C.S. File 54/14-15A & 16A

Looked for, not found.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #1059, surveyed April/Dec. 1981 - (DCSO records Vol. 45 Page(s) 17324)

The ¼ sec. cor., perpetuated and recorded by Haines in 1962, monumented with a wood post, 3" square, firmly set, projecting 12" above ground with scribe marks ¼ S visible on N. face, from which the remains of an original bearing tree:
A sawed Fir stump 48" dia., bears N.51°W., 69 lks. dist., with axe marks visible on bark.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 21 S R 5 W
1/4 S 20
 S 29

from which new bearing trees:
A Fir 11" dia., bears N.6½°E., 36 lks. dist., mkd. ¼ S20 BT.
A Fir 6" dia., bears S.41°W., 22½ lks. dist., mkd. ¼ S29 BT.

Reset the wood post alongside the iron post.
The corner is located at intersection of wire fences extending generally S., E., W.

Fd ok by D.Edwards, 2/2001 - M136-67