

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 806)

Set ¼ sec. post, from which
 A Cedar 15" dia., bears N.43°E., 83 lks. dist.
 An Alder 6" dia., bears S.44°W., 16 lks. dist.

Gilbert A. Gardner - Wit: Robert Barta - Dec. 15, 1955 - C.S. File 42/34

No evidence of old bearing trees found, logging having destroyed or removed them.
At one half the distance between section corners, set a 4" x 4" x 4 ft. Cedar stake for corner and marked:
 20" Red Fir N.57°W., 29 ft.
 10" Alder S.59°W., 23 ft.

Fd. Corner, Dec. 1967 by Haines - M 35-12

BLM Resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1639, surveyed Sept. 1992/April 1993. - (DCSO records Vol. 51 Page(s) 19406-07)

The ¼ sec. cor., reestablished by Gardner in 1955, recovered by Haines in 1967 and is accepted as the corner, determined from bearing trees mkd. by Gardner:
 An Alder 11" dia., bears S.59¼°W., 35 lks. dist., no marks visible on open and rotted blaze.
 A Fir 34" dia., bears N.57¼°W., 44 lks. dist., with duple healed blaze.
At the corner point
Drive a spike 10" long, 3/8" dia. 8" into the base of a 12" double trunk Alder, from which
 A stainless steel post, 28" long, 2½" dia., set 26" in the ground, for a reference monument, bears S.80°W., 30 lks. dist., with brass cap mkd. RM 19.8 FT TO COR S27 1993 and an arrow pointing to the corner.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.