

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 784)

Set post cor. of secs. 2, 3, 34 and 35, from which
A R.Fir 20" dia., bears N.59°E., 25 lks. dist.
A R.Fir 18" dia., bears N.10°W., 47 lks. dist.
A R.Fir 30" dia., bears S.15°E., 54 lks. dist.
A Cedar 10" dia., bears S.30°W., 33 lks. dist.

Fd. and used in GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 817)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1965 - C.S. File 54/14-2

Found - Orig. 16" now 22" Fir, N.59°E., 16.5 ft., probably 10 lk. error in dist., should be 23.1 ft., shows scribe in 6.0 ft. stump.
Orig. 30" now 44" Fir, S.15°E., 35.6 ft., shows bark scribe.
Orig. 12" now 25" Cedar, S.30°W., 21.8 ft., open face rotted. No scribe found. Alive.
No trace NW. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 20 S
R S 34 | S 35
5 S 3 | S 2
W T 21 S
1965

New BTs- 6" Hemlock S.87°W., 23.3 ft. mkd. S3 DCS BT.
7" D.Fir S.77°E., 21.4 ft. mkd. T21S R5W S2 DCS BT
No trees available to North.

BLM Resurvey by Floyd A. Brooks and Timothy A. Kent, Cadastral Surveyors, under Group #648, Surveyed Aug. 1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15258)

The Sec. Cor., remonumented by Tracy in 1965, with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap mkd. in 1965, from which the remains of the original bearing trees:

A Fir snag 20" dia., bears N.59°E., 27 lks. dist., with scribe marks S35 T20S R5W visible on open blaze. (Rec. 25 lks.)

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35, T20-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 42" dia., bears S.15°E., 54 lks. dist., with scribe marks S2 T21S R5W visible on bark blaze.
A Cedar 25" dia., bears S.30°W., 33 lks. dist., no marks visible on decayed face of open blaze.
and bearing trees mkd. by Tracy:
A Fir 8" dia., bears S.77°E., 32 lks. dist., with scribe marks T21S R5W S2 CS BT visible on an open double blaze.
A Hemlock 6" dia., bears S.87°W., 36 lks. dist., with scribe marks S3 DCS BT visible on open double blaze.
and new bearing trees:
A Fir 6" dia., bears N.50°E., 83½ lks. dist. mkd. T20S R5W S35 BT.
A Fir 8" dia., bears S.19°W., 62 lks. dist. mkd. T21S R5W S3 BT.
A Fir 7" dia., bears N.42°W., 53 lks. dist. mkd. T20S R5W S34 BT.
Add the marks BLM 1968 to the brass cap.

Note this is on the Douglas & Lane Co. line - check with Lane Co for more corner information.