

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T22-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 694)

-----  
 Set post corner of secs. 5, 6, 31 and 32; from which  
 A Hemlock 24" dia., bears N.30°W., 22 lks. dist.  
 A Fir 84" dia., bears N.55°E., 18 lks. dist.  
 A Fir 40" dia., bears S.32°E., 50 lks. dist.  
 A Fir 48" dia., bears S.72°W., 45 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #514, dated Aug. 27, 1884 (DCSO records Vol. 2 Page(s) 703)

-----  
 Place where cor. stood, Post gone and 3 bearing trees standing. Reestablished the cor. by setting post, 6" dia., 4 ft. long, with mkd. stone, 12" in ground, mkd. T21S S32 on NE.; R6W S5 on SE.; T22S S6 on SW.; S31 on NW. face, with 5 notches on E. and 1 on West edges; from which  
 Fir 70" dia., bears N.56°E., 19 lks. dist. mkd. T21S R6W S32 BT.  
 Fir 36" dia., bears N.30°W., 22 lks. dist. mkd. T21S R6W S31 BT.  
 Hemlock 24" dia., bears S.33°E., 50 lks. dist. mkd. T22S R6W S5 BT.  
 Cedar 24" dia., bears S.4°W., 42 lks. dist. mkd. T22S R6W S6 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy; C. Putnam, crew - Sept 11, 1961 - C.S. File 49/143-76

-----  
 Found - 40" Fir S.33°E., 33.0 ft. with faint bark scribing "S5" recognized.  
 80" Fir stump N.56°E., 12.5 ft. with traces of old bark scribing visible.  
 Stump hole S.4°W., 27.7 ft.  
 Stump hole N.30°W., 14.5 ft.

Set Brass cap at cor. mkd: County Surveyors Office  
 T 21 S  
 S 31 | S 32  
 S 6 | S 5 R6W  
 1961

New BTs -32" R.Cedar N.70°W., 17.0 ft. mkd. T21S R6W S31 CSBT  
 6" Hemlock N.19½°E., 20.2 ft. mkd. T21S R6W S32 CSBT  
 16" Hemlock S.48°W., 28.8 ft. mkd. T22S R6W S6 CS BT  
 Rescribe (in wood) 40" Fir S.33°E., 35.0 ft., to center of tree, mkd. T22S R6W S5 CS BT.

(Cont. Next Page)

