TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 729)

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 16, 17, 20, & 21, mkd. T 21 S S 16 on NE, R 6 W S 21 on SE, S 20 on SW, S 17 on NW face, with 4 notches on E & 3 on S edge; from which

Fir, 40" dia. bears N.14°E., 34 lks. mkd: T21S R6W S16 BT.
Hemlock, 24" dia., bears S.69°E., 16 lks., mkd: T21S R6W S21 BT.
V.Maple, 6" dia., bears S.60°W., 11 lks., mkd: T21S R6W S20 BT.
Fir, 36" dia. bears N.15°W., 72 lks. mkd: T21S R6W S17 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy, Clete Putnam - Nov. 13, 1961 - C.S. File 49/143-10

Found - Rotten Fir snag, N.15°W., 44 ft. instead of 47.5 ft., good bark scribing visible "T21S R6W S17"
Fir tree, now 68" N.14°E., 22.4 ft. to face. Traces of faint bark scribing visible. "S" is all I can recognize. Blaze & rescribe this tree "T21S R6W S16 CS BT"
Hemlock, now 42", S.69°E., 10.6 ft. (to face) Blaze & rescribe "T21S R6W S21 CS BT" No trace of SW BT

Set - Brass cap mkd: COUNTY SURVEYORS T21S R6W S17|S16
OFFICE, 1961 S20|S21

New BTs- 11" Hemlock N.68°W. 101.5 ft. mkd: T21S R6W S17 CSBT
17" Hemlock S.67½°W. 73.0 ft. mkd: T21S R6W S20 CSBT