

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only, T20-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by J. H. McClung, under Contract #173, dated July 20, 1872 - (DCSO records Vol. 2 Page(s) 679-80)

-----  
Set post for cor. to secs. 3, 4, 33 and 34, from which  
A Fir 48" dia., bears S.75°W., 48 lks. dist.  
A Fir 48" dia., bears N.71°E., 32 lks. dist.  
A Fir 14" dia., bears N.62½°W., 23 lks. dist.  
A Cedar 6" dia., bears S.47°W., 25 lks. dist.

Fd. and used in GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 725)

N.E. Richardson, Surveyor - Wit: Evans; Kershner - July 22, 1948 - C.S. File 39/176

-----  
Set 1" Galv. I.P. with a brass cap marked "Co. Surv. Office T20S R6W S33 S34, from which  
24" Fir bears N.25°W., 35.1 ft. dist. (New BT)  
4 ft. stump bears N.71°W., 21.1 ft. dist. (OBT scribe marks still good.)

Fd. OK Nov. 1983 by Lloyd Smith - M 95-49

BLM Resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #1231, Surveyed Sept. 1984/May 1985 - (DCSO records Vol. 47 Page(s) 18056)

-----  
The cor. of secs. 33 and 34, perpetuated and recorded by Richardson in 1948, monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground with brass cap mkd. in 1948, from which the remains of an original bearing tree:  
A sawed Fir stump 64" dia., bears N.71°E., 32 lks. dist., with scribe marks ¼ visible on opened blaze.  
and a bearing tree mkd. by Richardson:  
A Fir 36" dia., bears N.24°W., 53 lks. dist., with healed blaze.  
and a new bearing tree:  
A Maple 9" dia., bears N.19°E., 53 lks. dist. mkd. T20S R6W S34 BT.  
The corner is located in a barbed wire fence line, extending E. and W.

(Cont. Next Page)

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 373700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only, T20-6

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Survey by Steven Ness - For: Weyerhaeuser Co. - Oct. 14, 1994  
- M 121-24 A&B

-----  
CONDITION REPORT ONLY

Found - 2½" DCSO brass cap on 1½" Iron pipe.  
54" D.Fir N.80°W., 38 ft., large face partially  
opened, no marks visible. (No record)  
38" D.Fir N.29½°W., 25 ft., two large healed faces.  
(Rec. N.25°W., 35 ft.)

Fd. OK by D. Edwards, June 1999 - M131-70  
Fd. OK by T. Baker, Sept. 2006 - M151-48

Ronald L. Rice, Ward NW - Seneca Jones Timber Co. - May 2010  
- M 160-58

-----  
Found - 2½" DCSO brass cap with the following accessories:  
57" D.Fir bears N.80°W., 38.0' - healed face.  
39" D.Fir bears N.29½°W., 25.0' - healed face.  
31" D.Fir bears N.79°E., 91.7' - scribing visible.  
49" D.Fir bears N.67°E., 23.0' - scribing visible.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor  
and Robert H Browning, Survey Tech, Under Group No. 2268,  
Surveyed March/July 2009 - DCSO records Vol. 57 Page 22616

-----  
The cor. of secs. 33 & 34 only, monumented with an iron post,  
2½" dia., firmly set, projecting 8" above the ground, with  
brass cap (properly) mkd.

from which the remains of an original bearing tree

A sawed, decayed fir stump, 49" dia., bears N.71°E., 21.1  
ft., with scribe marks BT visible on an opened blaze.  
and a bearing tree mkd. by Richardson, in 1948

A fir, 37" dia., bears N.24°W., 35.0 ft., with a healed  
blaze.

and new bearing tree

A fir, 32" dia., bears N.78¾°E., 91.7 ft., mkd. T20S R6W  
S34 BT.

NAD 1983 (CORS))

Latitude: 43°46'49.315"N Longitude: 123°24'34.070" W