

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33, & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 718)

-----  
Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 27, 28, 33, & 34, mkd. T 21 S S 27 on NE, R 6 W S 34 on SE, S 33 on SW, S 28 on NW face, with 3 notches on E & 1 on S edge; from which  
    Fir, 24" dia. bears N.82°E., 20 lks. mkd: T21S R6W S27 BT.  
    Fir, 36" dia. bears S.51°E., 56 lks. mkd: T21S R6W S34 BT.  
    Dogwood, 3" dia., bears S.53°W., 13 lks., mkd: T21S R6W S33 BT.  
    Fir, 7" dia., bears N.49°W., 30 lks. mkd: T21S R6W S28 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey - 1961 - C.S. File 49/143-2+

-----  
Looked for & not found.

Wilford Haines - For: Woolley Logging - Surveyed 1965, plated March 1967 - M32-71

-----  
Found - 24" Fir, now stump, N.82°E., 20 lks.  
          36" Fir, dead & down, S.51°E., 56 lks.  
Set - ½" steel rod & scribed  
      12" Fir S.72°W., 234.8 ft.  
      28" Fir N.86°W., 121.2 ft.  
      16" Fir N.1°43'E., 135.5 ft.

Note - Corner is in ditch of road.  
This corner was set after road was constructed in 1966

Douglas Co. Surveyors Office - V.R. Tracy - April 3, 1967 C.S. File 54/14-33A

-----  
Fd. Haines' ½" I.R. set for cor. on S edge of new access road & BTs mkd by Haines & recorded on M32-71. We find no trace orig. BTs at this time. Note: Haines BT to NW is scribe 7 ft. above present road fill.

-----  
This note was added to the previous corner renewal system & signed by James Byron:  
These corner(s) searched for & orig. not fd. in 1961 by MEG, see C.S. File No. 49/143. V.R. Tracy returned to same corner(s) in April 1967 not sufficient evidence, see C.S. File 54/14-33A.  
Added 3/15/2005 DCSO, JC.

continued next page

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33, & 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Dependent resurvey by Wayne Rogers & Dale Bedell, Cadastral Surveyors, under Group #1392, surveyed Aug./Nov. 1987 - (DCSO records Vol. 48 Page(s) 18469)

-----  
The secs. 27, 28, 33 & 34, perpetuated & recorded by Haines in 1967, monumented with an iron rod, 5/8" dia., firmly set, projecting 2" above the ground, from which the remains of the BTs mkd. by Haines:

- A fir, 20" dia., bears N.2°E., 205 lks. with healed blaze.
- A fir, 20" dia., bears S.72°W., 356 lks. with healed blaze.
- A fir snag, 30" dia., bears N.86°W., 184 lks. with healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T21S	R6W
S 28	S 27
S 33	S 34
1987	

from which a new BT

- A fir, 8" dia. bears N.65°W. 73½ lks. mkd: T21S R6W S28 BT
- No suitable tree available in Sec. 34

Deposit white "DEEP-1" magnetic marker at base of stainless steel post & the iron rod along side.

The corner is 15 lks, S of a dirt road, 20 lks, wide, bears N.85°E., & S.85°W.

Fd. Ok by Les Roberts 2/1994 - M118-39

Ronald L Rice - For: Seneca Jones Timber Co. - Mar 2015 - M169-17

-----  
Found - 1987 BLM brass cap with the following accessories:  
32" D.Fir bears N.2°E., 135.3' - healed face.  
27" D.Fir bears S.72°W., 235.0' - healed face.  
Record 30" Fir snag N.86°W., 121.4'- down rotted hollow shell  
18" D.Fir bears N.65°W., 48.5' - healed face  
Steel post adjacent to corner.