

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 716)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked ¼ S on N face; from which Cedar, 16" dia., bears N.72°W., 30 lks., mkd: ¼ S BT.
Hemlock, 20" dia., bears S.50°E., 16 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo Godfrey, Deputy - V. Tracy; Clete Putnam, crew - Dec. 1961 - C.S. File 49/143-16

Found - Hemlock, now 36", S.50°E., 10.6 ft. scribing visible thru old opening to face, "¼S"
Cedar tree, now 33" N.72°W., 19.8 ft., shows old scars, has been opened previously. Old face rotted away, entire center gone.

Set - Brass cap at cor. mkd:
County Surveyor's T21S R6W ¼ S 2
Office, 1961 S 11
New BTs- 8" Hemlock N.59½°W., 22.4 ft., mkd: ¼ S2 CS BT
11" Hemlock S.69½°E., 32.5 ft., mkd: ¼ S11 CS BT
This corner lies about 40 ft. south of Peterson Creek.

Fd. Ok by L. Roberts 12/1992 - M116-43 & C.S. File 63/149-3J