

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 & 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 707)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which
Fir, 40" dia., bears N.31°E., 23 lks., mkd: ¼ S BT.
Fir, 36" dia., bears S.50°E., 61 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Clete Putnam - Dec. 1961 - C.S. File 49/143-18

Found - Squared cedar stake.
48" fir stump N.31°E., 15.0 ft. scribed "¼ S12 BT" scribing probably 10-20 yrs old. Definitely not orig., I doubt if stump is big enough to have been 40" tree in 1884.
No metal or stone monument found. No evidence of orig. BTs.

BLM Dependent resurvey by Lance J. Bishop & Wayne Rogers, Cadastral Surveyors, under Group #1158, surveyed Oct. 1983 - (DCSO records Vol. 47 Page(s) 17814-5)

The ¼ sec. cor. of secs. 12 & 13, determined from the remains of the orig. BTs:
A sawed fir stump, 48" dia., bears N.31°E., 23 lks., with scribe marks ¼ S12 BT visible on opened blaze.
A decayed fir stump, 34" dia., bears S.50°E., 61 lks., no marks visible.
At the corner point
Set an iron post, 28" long, 2½" dia., 25" in the ground, with brass cap marked:
T21S R6W
¼ S 12
S 13
1983
from which new BTs
A fir, 12" dia., bears S.16½°E., 44 lks., mkd: ¼ S13 BT.
A fir, 8" dia., bears N.33½°W., 8 lks., mkd: ¼ S12 BT.