

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. corner)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 633-634)

Set post cor. of Tps. 21 and 22 S., Ranges 7 & 8 W.; from which

- A Hemlock 8" dia., bears N.54°E., 34 lks. dist.
- A Cedar 12" dia., bears S.30°E., 28 lks. dist.
- A Cedar 18" dia., bears N.30°W., 55 lks. dist.
- A Cedar 12" dia., bears S.40°W., 50 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan 22, 1881 (DCSO records Vol. 4 Page(s) 1534)

Township cor., set new stake, bearing trees all standing.

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 2 Page 558-559)

I found post decayed and trees standing. Reestablished the corner by setting a post, 4½ ft. long, 4½" dia., 24" in ground,, mkd. T21S S31 on NE.; R7W S6 on SE.; T22S S1 on SW.; R8W S36 on NW. face, with 6 notches on each edge; from which

- A Hemlock 8" dia., bears N.55°E., 32 lks. dist. mkd. T21S R7W S31 BT.
- A Cedar 12" dia., bears S.30°E., 28 lks. dist. mkd. T22S R7W S6 BT.
- A Cedar 18" dia., bears N.30°W., 55 lks. dist. mkd. T21S R8W S36 BT.
- A Cedar 12" dia., bears S.40°W., 50 lks. dist. mkd. T22S R8W S1 BT.

BLM resurvey by Lytle, Palmer, Tillman, Bicknell, Gawron and Thielsen, Cadastral Surveyors, under Group #304, surveyed Aug. 1952/Oct. 1954 (DCSO records Vol. 30 Page(s) 12542-43)

At the cor. of Tps. 21 and 22 S., Rs. 7 and 8 W., determined from the remains of three original bearing trees:

- A Cedar 45" dia., bears S.30°E., 28 lks. dist., showing a healed blaze facing NW.
- A stump hole of a Cedar bears S.40°W., 50 lks. dist.
- A Cedar stump, bears N.30°W., 55 lks. dist., showing evidence of axe marks on SE. face.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. Corner)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Set an iron post 3 ft. long, 3" dia., 26" in the ground, with brass cap mkd:

T 21 S
R 8 W | R 7 W
S 36 | S 31
S 1 | S 6
T 22 S
1952

from which

- A Cedar 10" dia., bears N.50½°E., 43 lks. dist. mkd. T21S R7W S31 BT.
- A Cedar 45" dia., bears S.30°E., 28 lks. dist. mkd. T22S R7W S6 BT.
- A Hemlock 15" dia., bears S.34½°W., 26 lks. dist. mkd. T22S R8W S1 BT.
- A Fir 12" dia., bears N.42°45'W., 89 lks. dist. mkd. T21S R8W S36 BT.

Fd. Ok by Gary Smithers - May 2005 - C.S. File 65/54-23

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2114, surveyed Sept. 2005/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21626)

The cor. of Tps. 21 and 22 S., Rgs. 7 and 8 W., monumented with an iron post, 3" dia., firmly set, projecting 6" above ground, with brass cap mkd.

from which the remains of the original bearing trees

A cedar, 56" dia., bears S.30°E., 18.5 ft., with a healed blaze.

A roothole bears N.30°W., 36.3 ft., with a down cedar, 30" dia., alongside, no marks visible.

and the bearing trees mkd. by Lytle, et al., in 1952-54

A cedar, 27" dia., bears N.50½°E., 28.4 ft., with a healed blaze.

A hemlock, 25" dia., bears S.34½°W., 17.2 ft., with a healed blaze.

A fir, 30" dia., bears N.42¾°W., 58.7 ft., with a healed blaze.

A steel fence post is alongside the cor.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2115, surveyed January/May 2007 (DCSO records Vol. 56 Page(s) 22046-7)

The cor. of Tps. 21 and 22 S., Rgs. 7 and 8 W., monumented with an iron post, 3" dia., firmly set, projecting 6 ins. above ground, with brass cap (properly) mkd.

continued next page

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. corner)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees
A cedar, 56" dia., bears S.30°E., 18.5 ft., with a healed
blaze.
A roothole bears N.30°W., 36.3 ft., with a down cedar, 30"
dia., alongside, no marks visible.
and bearing trees mkd. by Lytle, et al., in 1952-54
A cedar, 27" dia., bears N.50½°E., 28.4 ft., with a healed
blaze.
A hemlock, 25" dia., bears S.34½°W., 17.2 ft., with a
healed blaze.
A fir, 30" dia., bears N.42¾°W., 58.7 ft., with a healed
blaze.
A steel fence post is alongside the cor.