

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 672)

Fir, 30" dia., for qr. sec. cor., marked ¼ S on N face; from which

Fir, 24" dia., bears N.5°E., 58 lks., mkd: ¼ S BT.

Fir, 14" dia., bears N.70°W., 10 lks., mkd: ¼ S BT.

BLM dependent resurvey by Donald R. Beck, Cadastral Surveyor, under group #655, surveyed Sept./Oct. 1967 - (DCSO records Vol. 34 Page(s) 14164-5)

Point for the ¼ sec. cor. of secs. 18 & 19, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 21" in the ground with brass cap marked:

T 21 S R 7 W

¼ $\frac{S\ 18}{S\ 19}$

1967

from which

A cedar, 17" dia., bears N.60°W., 40 lks., mkd: ¼ S18 BT.

A cedar, 15" dia., bears S.27°W., 34 lks., mkd: ¼ S19 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2114, surveyed Sept. 2005/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21651)

The ¼ sec. cor. of secs. 18 and 19, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Beck in 1967

A cedar, 21" dia., bears S.27°W., 23.3 ft., with a healed blaze. (Record, 22.4 ft.)

A decayed cedar stump, 14" dia., bears N.61¾°W., 27.6 ft., with illegible marks visible on partially healed blaze. (Record, N.60°W., 26.4 ft.)

and a new bearing tree

A hemlock, 8" dia., bears N.4°W., 32.9 ft., mkd. ¼ S18 BT.

The geographic position (NAD 1983 (91)) of the quarter corner of sections 18 and 19, as determined by a tie from a GPS observation on a temporary monument processed using the National Geodetic Survey's OPUS, in 2006, is as follows:

Latitude: 43°44'06.00" N. Longitude: 123°34'29.77" W