

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Cor Secs 7, 8, 17, & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Pages 672-3)

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 7, 8, 17, & 18, mkd. T 21 S 8 on NE, R 7 W S 17 on SE, S 18 on SW, S 7 on NW face, with 5 notches on E & 4 on S edges; from which
 Fir, 8" dia., bears N.19°W., 25 lks., mkd: T21S R7W S7 BT.
 Oak, 5" dia., bears N.33°E., 18 lks., mkd: T21S R7W S8 BT.
 Oak, 7" dia., bears S.67°E., 17 lks. mkd: T21S R7W S17 BT.
 Oak, 5" dia., bears S.10°W., 5 lks. mkd: T21S R7W S18 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey, S. Bilow - Aug. 5, 1958 - C.S. File 49/20-5

Found - Orig. 8", now 30" Fir N.19°W., 16.5 ft. I open & find good scribe marks "S".
I find no Oaks in this vicinity.
I do find Chinquapin which are not old enough to be orig., that check good for rec. dist. & bearing for other BTs.
Set brass cap at corner mkd: $\frac{S7}{S18} | \frac{S8}{S17}$ 21S R7W County Surveyors Office, 1958
New BTs- 10" R.Fir N.7½°E., 17.3 ft., mkd: S8 T21S R7W CS BT
 12" R.Fir S.64½°W., 23.0 ft. mkd: S18 T21S R7W CS BT
 8" R.Fir N.40°W., 34.4 ft., mkd: S7 CS BT
 8" R.Fir S.78°E., 23.0 ft., mkd: S17 T21S R7W CS BT

BLM dependent resurvey by Donald R. Beck, Cadastral Surveyor, under group #655, surveyed Sept./Oct. 1967 - (DCSO records Vol. 34 Page(s) 14166)

The cor. of secs. 7, 8, 17, & 18, perpetuated & recorded by Byron in 1958, monumented with an iron post, 1½" dia., firmly set, protruding 6" above ground, with brass cap properly mkd. from which the remaining orig. BT:
 A down fir, 30" dia., N.19°W., 25 lks., with scribe mark S visible on partially opened blaze.
and BTs by Byron
 A fir, 13" dia., bears N.15°E., 38 lks., mkd: T21S R7W S8 BT on partially healed blaze.
 A chinquapin, 9" dia., N.88°E., 41 lks., mkd: T21S R7W S17 BT on partially healed blaze.
and new BTs
 A Fir, 33" dia., bears S.64°E., 120 lks., mkd: T21S R7W S17 BT.
 A Fir, 18" dia. bears N.46°W., 65 lks. mkd: T21S R7W S7 BT
No other suitable tree available within limits.

PRIMARY CORNER DESCRIPTION Cor Secs 7, 8, 17, & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - L. E. Monrean - P.L. Earle & J.H. Cook - 10/28/1975 - C.S. File 57/36-23

-
- Found - 10" now 11" dia. fir scribed "S8 21S R7W" partially healed over, tagged partially uprooted and leaning heavily.
 - 8" now 9" dia. Fir has good blaze-did not open, tagged.
 - 8" dia. chinquapin scribed "S17 T21S R1W CS BT" Tagged.
 - 33" now 33½" dia., fir has good blaze - did not open - tagged
 - 18" now 18½" dia. fir has good blaze did not open - tagged.
 - 8" now 30" dia. fir is down, has been opened and is rotted. Tagged

Set Brass cap at section corner marked: T21S R7W
 County Surveyor's Office S7 | S8
 1975 S18 | S17

- BT - 11" dia. Fir (see Found #1) Scribed "S 8 T21S R7W CSBT" bears N.6°E., 17.0 ft. (record N.7½°E., 17.3 ft.)
- 9" dia Fir (see Fd. #2) scribed "S7 CS BT" bears N. 40°W., 34.9 ft. (record N.40°W., 34.4 ft.)
- 8" dia chinquapin (see Fd. #3) scribed "S 17 T21S R7W CS BT" bears S.80°E., 23.0 ft. (record per renewal S.78°E., 23.0 ft; record per Gov't survey N.88°E., 27.1 ft.)
- 33.5" dia. fir (see fd. #4) scribed "T21S R7W S17 BT" bears S.59½°E., 80.8 ft. (Record per Gov't survey S.64°E., 79.7 ft)
- 18.5" dia. Fir (see fd.#5) scribed "T21S R7W S7 BT" bears N.52°W., 42.6 ft. (record per Gov't survey N.46°W., 42.9 ft.)
- 30" dia. Fir (see fd #6) bears N.23°W., 11.5 ft. (orig. N.19°W., 16.5 ft.)

No new bearing trees scribed as sec. 18 has no substantial trees in area of corner. Corner lies approx. 60' easterly of BLM Rd. #21-7-22: line crossing tag on westerly side of Road. Corner lies near the top of slide area. The corner and all accessories lie on a westerly slope with signs of severe shifting.