

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 675)

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 5, 6, 7, & 8, mkd. T 21 S S 5 on NE, R 7 W S 8 on SE, S 7 on SW, S 6 on NW face, with 5 notches on S & E edges; from which

- Hemlock, 20" dia., bears S.45°E., 46 lks., mkd: T21S R7W S8 BT.
- Hemlock, 18" dia., bears S.12°W., 41 lks., mkd: T21S R7W S7 BT.
- Hemlock, 18" dia., bears N.61°E., 35 lks., mkd: T21S R7W S5 BT.
- Hemlock, 24" dia., bears N.13°W., 18 lks., mkd: T21S R7W S6 BT.

BLM monumentation of certain corners by Floyd A. Brooks, Cadastral Surveyor, under group #350, surveyed Aug. 30, 1967 - (DCSO records Vol. 34 Page(s) 14278)

The cor. of secs. 5, 6, 7, & 8, determined at the record bearing & dist. from the orig. BTs:

- A Hemlock, 28" dia., bears N.61°E., 35 lks., with no marks visible on decayed blaze.
- A decayed Hemlock stump, 18" dia., bears S.12°W., 41 lks., with no marks remaining.
- A Fir, 52" dia., bears N.13°W., 18 lks., with fragmentary scribe marks visible on bark blaze. (Rec. Hemlock)

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T21S R7W
S 6 | S 5
S 7 | S 8
1965

from which new BTs

- A Hemlock, 7" dia., bears N.31½°E., 69 lks., mkd: T21S R7W S5 BT.
- A Hemlock, 10" dia., bears S.13°E., 25 lks., mkd: T21S R7W S8 BT.
- A Hemlock, 12" dia., bears S.28°W., 34 lks., mkd: T21S R7W S7 BT.
- A Hemlock, 25" dia., bears N.61°W., 64½ lks., mkd: T21S R7W S6 BT.