

PRIMARY CORNER DESCRIPTION N 1/16 Cor. Secs. 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Floyd A. Brooks & James E. Jelley, Cadastral Surveyors, under group 350 & 536, surveyed May/June 1964 - (DCSO records Vol. 32 Page(s) 13518-9)

Point for the N 1/16 secs. cor. of secs. 20 & 21
Set an iron post, 28" long, 2½" dia., 16" in the ground, to solid rock, & in a mound of stone, 3 ft. base, to top, with brass cap marked:
N 1/16
S 20|S 21

from which
A Fir, 15" dia., bears N.67½°E., 105 lks., mkd: N 1/16 S21 BT.
A Hemlock, 15" dia., bears S.3°W., 73 lks., mkd: N 1/16 S20 BT.

Wilford Haines - Jan. 8, 1973 - C.S. File 51/309

Replaced orig. brass cap lost during road construction with brass cap placed 1" above ground inscribed as follows:
T 21 S R 7 W
N 1/16
S 20 S 21
RS 239

Found - Orig. 15" D.Fir, now stump, 105 lks., S.67½°W. Good shape with yellow BT tag.
Orig. 15" Hemlock, top out, 73 lks., N.3°E. Good shape with yellow BT tag.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2114, surveyed Sept. 2005/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21634)

The N 1/16 sec. cor. of secs. 20 and 21, remonumented by Haines, in 1973; monumented with an iron post, 1" dia., firmly set, projecting 9" above ground, with brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Brooks and Jelley in 1964

A decayed fir stump, covered with road fill, flush with surface, size indeterminate, bears N.65¾°E., 69.3 ft., no marks visible. (Record, N.67½°E.)

A hemlock, 24" dia., bears S.3°W., 48.2 ft., with a healed blaze.

and a new bearing tree

A fir, 51" dia. bears S.86½°E. 101.6 ft. mkd. N1/16 S21 BT
Corner is located in heavy alder blowdown in road clearing, on the NE. cor. of fir reproduction, edge bears S. and W