

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 649-50)

A Fir, 10" dia., for cor. to secs. 33, 34, 28 & 27, mkd. T 21 S S 27 on NE, R 7 W S 34 on SE, S 33 on SW, S 28 on NW face, with 3 notches on E & 1 notch on S edges; from which

Fir, 10" dia., bears N.40°E., 33 lks. mkd: T21S R7W S27 BT

Fir, 20" dia., bears N.64°W., 6 lks., mkd: T21S R7W S28 BT

Fir, 16" dia., bears S.30°E., 9 lks., mkd: T21S R7W S34 BT

Fir, 18" dia., bears S.35°W., 8 lks. mkd: T21S R7W S33 BT

Wilford N. Haines - Oct. 1962 - C.S. File 51/222-7

Found - 10" Fir corner tree & orig. BTs:
 10" Fir, now 24" N.40°E., 33 lks., 21.78 ft. rescribed on N side.
 20" Fir N.64°W., 6 lks. = 3.96 ft. (Gone)

New - 5" Fir S.19°W., 3.1 ft.
 4" Fir N.65°W., 5.6 ft.

Corner tree is now dead & almost all burned.
 Set - 1"x1"x36" T iron in center of shell.

BLM dependent resurvey by Floyd A. Brooks & James E. Jelley, Cadastral Surveyors, under group 350 & 536, surveyed May/June 1964 - (DCSO records Vol. 32 Page(s) 13514)

The cor. of secs. 27, 28, 33, & 34; established by Wheeler in 1883; remonumented by Haines, in 1961, with a 1" "T" iron, 36" long, driven 24" into decayed stump of orig. corner tree, from which the remaining original bearing trees:

A fir, 20" dia., bears N.40°E., 33 lks., with a healed blaze. This tree remarked T21S R7W S27 BT by Haines on a double blaze.

A down and decayed fir, 16" dia., bears S.30°E., 9 lks., with no marks remaining on opened and decayed blaze. and trees marked by Haines

A fir, 6" dia., bears S.13°W., 4½ lks., with scribe marks T21S R7W S33 BT visible on partly healed double blaze.

A fir, 5" dia., bears N.66½°W., 8 lks., with scribe marks T21S R7W S28 BT visible on partly healed double blaze.

At the corner point
 Remove decayed stump of orig. corner tree down to solid rock, 4" below ground level and set an iron post, 1" dia. 14" long, 6" in drill hole in solid rock, with brass cap marked

T21S	R7W
S 28	S 27
S 33	S 34

1964

continued next page

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33, & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>from which a new bearing tree A fir, 13" dia., bears S.26¼°E., 43½ lks., mkd. T21S R7W S34 BT. Deposit the Haines' monument alongside the corner post.</p>
<p>BLM Dependent resurvey by Wayne Rogers & Joel Robb, Cadastral Surveyors, under Group #1318, surveyed May/Nov. 1986 - (DCSO records Vol. 48 Page(s) 18314) ----- The cor. of secs. 27, 28, 33, & 34, monumented with an iron post, 1" diam., firmly set, projecting 3" above ground, alongside of which is lying a T iron, 36" long, 1" dia., The brass cap is mkd: T 21 S R 7 W S 28 S 27 S 33 S34 1964 From which the remaining orig. BT: A fir, 23" dia., bears N.40°E., 33 lks., with healed blaze. and bearing trees mkd. by Haines, in 1961. A fir, 6" dia., bears S.13°W., 4½ lks. with healed blaze. A fir, 6" dia., bears N.66½° W., 8 lks. with healed blaze. and a bearing tree mkd. by Brooks and Jelley A fir, 17" diam., bears S.23°E., 42 lks., with healed blaze. (Record, S.26½°E., 43½ lks.)</p>
<p>Fd. Ok by L. Roberts, 5/1999 - M131-62</p>
<p>Fd. & used on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1916, surveyed Aug. 1999/May 2000. (DCSO rec. Vol. 53 page(s) 20643-4)</p>
<p>Fd. OK 4/2018 by R. Quimby C.S. File 65/101-9</p>
<p>David Edwards - For: Roseburg Resources - May 2019 - M175-52 ----- Fd. As per record Set a six ft steel post 2 ft south.</p>
<p>David Edwards - For: Roseburg Resources - Jan. 2025 - M184-49 ----- Fd. As per record except NW BT dead. Set a 5.5' steel post 2'N on line.</p>
<p> </p>