

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 2 Page(s) 653)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked ¼ S on W face; from which
Fir, 20" dia., bears N.68°E., 19 lks., mkd: ¼ S BT.
Fir, 30" dia., bears S.72°W., 28 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - C. Putman - July 9, 1959 - C.S. File 49/20-8

Found - Point of rotted Oak stake at corner.
40" Fir N.68°E., 12.5 ft. chopped open & found scribe "S".
48" Fir S.72°W., 18.5 ft.

At corner set iron pipe with brass cap mkd:
County Surveyors Office
1959 T21S R7W ¼ S16/S15

Blaze & scribe following trees:
11" Hemlock N.8½°W., 35.5 ft. mkd: "¼ S16 CS BT"
18" Fir S.48½°E., 12.8 ft. mkd: "¼ S15 CS BT"

Douglas Co. Surveyors Office - Milo Godfrey & Crew - Dec. 20, 1963 - C.S. File 49/20-18

Found - 40" Fir N.68°E., 12.5 ft. (Orig. BT fd. in 1959)
Tree alive & in good condition.
18" Fir S.48½°E., 12.8 ft. mkd. in 1959, scar pitched over & nearly healed.
58" Fir to the SW (orig. BT) is uprooted & down.
Hemlock to the NW marked in 1959 is gone.
Did not find brass cap set in 1959.

Set - Brass cap at cor. mkd: County Surveyors Office 1963
T21S R7W ¼ S16/S15

New BTs- 13" Hemlock S.30°W., 37.3 ft., mkd: ¼ S16 CS BT
Note - Corner lies approx. 100 ft. north of ridge top.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2619, Surveyed March/May 2011 - (DCS0 records BLM Plat T21-7W 2012-1 & Vol. 58 Pages 22943-4)

The ¼ sec. cor. of secs. 15 & 16, perpetuated by Byron in 1959, subsequently perpetuated by Godfrey in 1963, monumented with an iron post, 1¼" dia., firmly set, projecting 5" above ground, with a brass cap (properly) marked.
from which the remains of an orig. BT

A sawed, decayed fir stump, 42" dia., bears N.68°E., 12.5 ft. with axe marks visible and a metal cover. CONT.

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

and the remains of a BT mkd by Godfrey
A decayed hemlock stump, size indeterminate, bears
S.30 $\frac{1}{4}$ °W., 36.1 ft. with no marks visible.

and new BTs

A fir, 13" dia., bears S.53 $\frac{1}{4}$ °E., 19.3 ft., mkd: $\frac{1}{4}$ S15 BT.

A fir, 14" dia., bears S.41 $\frac{1}{4}$ °W., 24.8 ft., mkd: $\frac{1}{4}$ S16 BT.

and a collar of stone around the iron post.

The iron post set by Byron, 36" long, 1 $\frac{1}{4}$ " dia., disturbed,
buried under a large rock, with a brass cap mkd. COUNTY
SURVEYORS OFFICE T21S $\frac{1}{4}$ S16 S15 R7W 1959, approx. 3 ft.
easterly and downhill of the cor. is exhumed and buried
alongside the cor.

(NAD 1983 (CORS 96))

Latitude 43°44'31.35"N Longitude 123°31'34.65"W