

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION C C for secs. 3 & 4 only (North)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 556)

-----  
Set post 5" dia., 4 ft. long, 24" in ground for closing cor. to secs. 3 & 4, marked T20S R7W S34 on N.; R7W S3 on SE.; T21S S4 on SW.; face, with 3 notches on E. and 3 on W. edges; from which

A Maple 14" dia., bears S.14°E., 21 lks. dist. mkd. T21S R7W S3 BT.

A Fir 40" dia., bears N.20°W., 72 lks. dist. mkd. T20S R7W S34 BT.

A Fir 36' dia., bears S.45°W., 47 lks. dist. mkd. T21S R7W S4 BT.

Fd. and Used in GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 572-73)

Wilford N. Haines, #239 & Leo Martin - For: Harold Woolley - Filed Jan. 21, 1958 - M 8-31

-----  
Set Lot marker from original BT to NW.  
Scribed- 9" Cedar S.55°W., 31.3 ft.  
12" Fir S.46°E., 22.8 ft.

Douglas Co. Surveyors Office - Gary Langlitz; P. Earle - Feb. 12, 1974 - C.S. File 56/43-13

-----  
Found - 1"x1" T-Iron with copper washer mkd. Wilford N Haines 239 Survey Point Drain Oregon.  
12" Red Cedar bears S.55°W., 31.3 ft. scribed "T21S R7W S4 CC BT" in open blaze.  
14" Fir now dead, bears S.51°E., 22.8 ft. (Rec. S.46°E., 22.8 ft.) with visible blaze.  
Orig. BT to the NW. is now a shattered stump with blaze portion missing.

Set brass cap alongside T Iron mkd: County Surveyors Office

T 20 S  
-----  
S 4 | S 3  
C C  
T21S R7W  
1974

No suitable trees near, I Mark:  
14" Red Cedar stump, bears S.11°E., 26.8 ft. scribed "CS BT".

Cor. lies at lower edge of old cat road.

(Cont. Next Page)

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1159, surveyed Aug. 1983/May 1984 - (DCSO records Vol. 47, Page(s) 18036)

-----  
The Sec. cor., perpetuated and recorded by Haines in 1958, and further perpetuated and recorded by Langlitz in 1974, monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground with brass cap mkd. by DCSO in 1974, from which the remains of the original bearing trees:

A sawed Maple stump 11" dia., bears S.14°E., 21 lks. dist., no marks visible.

A decayed Fir stump, size indeterminate, bears S.45°W., 47 lks. dist., no marks visible.

A sawed Fir stump 45" dia., bears N.20°W., 72 lks. dist., no marks visible.

and the remains of bearing trees mkd. by Haines:

A Fir snag 14" dia., bears S.51°E., 34½ lks. dist. with fragmentary scribe marks visible on partially healed blaze.

A Cedar 18" dia., bears S.55°W., 44½ lks. dist. with fragmentary scribe marks visible on partially healed blaze.

and the remains of a bearing tree mkd. by Langlitz:

A Cedar stump 14" dia., bears S.11°E., 41 lks. dist. with scribe marks CS BT visible on open blaze.

and a new bearing tree:

A Fir 5" dia., bears S.10°E., 9 lks. dist. mkd. X BT.