

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 2 Page(s) 653)</p> <p>-----</p> <p>Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked ¼ S on N face; from which Hemlock, 24" dia., bears N.63°E., 7 lks., mkd: ¼ S BT. Maple, 6" dia., bears S.30°W., 50 lks., mkd: ¼ S BT.</p>
<p>Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - C. Putman - July 9, 1959 - C.S. File 49/20-12</p> <p>-----</p> <p>Found - Hemlock snag, now 36", N.63°E., 4.6 ft. This snag had been chopped open to expose scribing "BT", plainly visible. Rotted remains of Maple S.30°W., 33 ft. chopped open &amp; fd. fragmentary but unmistakable scribe marks. At corner set iron pipe with brass cap mkd: County Surveyor's T21S R7W ¼ S15/S22 Office 1959</p> <p>Blaze &amp; scribe new BTs: 10" Hemlock N.21°E., 37.4 ft., mkd: ¼ S15 CS BT 15" R.Cedar S.81°W., 47.3 ft., mkd: ¼ S22 CS BT</p>
<p>Douglas Co. Surveyors Office - Gary L. Langlitz - Clell E. Goodwin - A. Vic Cangie - M. Lenora Ladig - 12/3/1975 - C.S. File 57/39-24</p> <p>-----</p> <p>Found - I Pipe with brass cap attached, firmly set &amp; marked as described by the County Surveyor in 1959. We find the orig. NE bearing as described in 1959. It bears N.63°E., 4.6 ft. The orig. SW BT has been destroyed. We find the CS BTs as follows: A 10" now 14" hemlock bears N.21°E., 37.4 ft. alive &amp; well healed. A 15" R.Cedar, now a stump bears S.81°W., 47.3 ft. partially buried in logging debris. We mark a new BT.</p> <p>New BT - A 12" maple stump with numerous sprouts growing from its top, bears S.22°W., 17.3 ft. scribed "¼ S22 CS BT" on a double blaze.</p> <p>Note - This corner lies along an E-W cutting line at the north edge of an existing clearcut, approx 250 ft. north &amp; 75 ft. lower than a paved BLM access road. Compass decl. 20°E.</p>
<p>continued next page</p>

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tony Hostetter - Feb. 2011 - C.S. File 65/72-2

-----

- Found - 1959 brass cap as set by Douglas County Surveyor (C.S. 49/20). From which:
  - 15" Cedar stump, BLM tag, sheet metal cap, bears: S.84°W., 47.3 ft.
- New BTS- 14" Hemlock, scribed "S15 ¼ BT", Roseburg tag, bears: N.68°E., 12.2 ft to spike placed in root collar below scribing.
- 10" Fir, scribed "S22 ¼ BT", Roseburg tag, bears: S.54°E., 21.2 ft to spike placed in root collar below scribing.
- 16" Alder, scribed "S22 ¼ BT", Roseburg tag, bears: S.86°E., 0.8 ft to spike placed in root collar below scribing.