

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 643)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked ¼ S on W face; from which
 Fir, 24" dia., bears N.71°E., 62 lks., mkd: ¼ S BT.
 Cedar, 60" dia., bears West, 54 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey & S. Bilow - May 23, 1958 - C.S. File 49/20-3

Found - Both orig. BTs
 Orig. 24" now 48" Fir stump N.71°E., 40.9 ft. shows good scar near base, I do not open.
 Orig. 60" now 68" Cedar West 35.6 ft., I open & find good scribing "1 4" BTs check for bearing & dist.
Set brass cap at corner mkd: ¼ S27/S26 T21S R7W County Surveyors Office, 1958
New BTs- 20" Cedar bears N.18°E. 97.5 ft. scribed ¼ S26 CS BT
 8" Hemlock bears S.39°W. 5.9 ft. scribed ¼ S27 CS BT

Fd. ok by Les Roberts 9/1992 - M 115-63

FD. ok on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1916, surveyed Aug. 1999/May 2000. (DCSO rec. Vol. 53 page(s) 20636)

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 12/11/2019 (filed 11/3/2022) - C.S. File 67/54-36

Reported as Fd OK