

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 881)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on N face from which:

Fir, 10" dia., bears N.5°W., 90 lks., mkd: 1/4 S BT.

Fir, 15" dia., bears S.31°E., 92 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11425)

Proportional measurement

Set an iron post, 3' long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked:

1/4 $\frac{S \ 7}{S \ 18}$
1945

from which

A fir, 70" dia., bears N.74°E., 42 lks., mkd: 1/4 S7 BT.

A fir, 70" dia., bears S.3 1/2°E., 36 lks., mkd: 1/4 S18 BT.

Fd ok - BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)

Mark Smalley - 11/2000 - C.S. File 65/33-15

Found - 1945 BC/IP

70" Fir, N.74°E., 42 lks., - rotten stump.

70" Fir, S.3 1/2°E., 36 lks., - rotten stump.

New BTs- 16" Fir, S.13°W., 11.6 ft. - scribed "1/4 S BT"

7" Fir, S.60°W., 7.9 ft. - scribed "1/4 S BT"

10" Fir, N.61°W., 10.7 ft. - scribed "1/4 S BT"

12" Fir, N.36°E., 29.8 ft. - scribed "1/4 S BT"