

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 875)

-----  
Set post 6" dia., 4 ft. long with marked stone 12" in ground for corner to secs. 19, 20, 29, & 30, marked T21S, S 20 on NE, R8W, S 29 on SE, S 30 on SW, S 19 on NW face with 5 notches on E and 1 on N edge from which:

- Hemlock, 6" dia., bears S.72°E., 13 lks., mkd: T21S R8W S29 BT.
- Fir, 60" dia., bears S.80°W., 16 lks., mkd: T21S R8W S30 BT.
- Fir, 40" dia., bears N.54°W., 62 lks., mkd: T21S R8W S19 BT.
- Cedar, 36" dia., bears N.40°E., 91 lks., mkd: T21S R8W S20 BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11417)

-----  
Proportional measurement,  
Set an iron post, 3' long, 2" dia., 28" in the ground, for cor. of secs. 19, 20, 29, & 30, with brass cap marked:

T21S R8W  
S 19|S 20  
S 30|S 29  
1945

from which

- A dead fir, 28" dia., bears N.72°E., 72 lks., mkd: T21S R8W S20 BT.
- A dead cedar, 32" dia., bears S.34½°E., 276 lks., mkd: T21S R8W S29 BT.
- A dead fir, 66" dia., bears S.22°W., 253 lks., mkd: T21S R8W S30 BT.
- A dead fir, 64" dia., bears N.21½°W., 83 lks., mkd: T21S R8W S19 BT.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20746-7)

-----  
The cor. of secs. 19, 20, 29, and 30, monumented with an iron post, 2" dia., firmly set, projecting 14" above the ground, with brass cap (properly) mkd.

from which the remains of a BT mkd. by Price and Rigby

- A fir stump, 32" dia., bears N.72°E., 47.5 ft., no marks visible.

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>A fir stump, 55" dia., bears N.21½°W., 54.8 ft., no marks visible. and new bearing trees A fir, 14" dia., bears N.51½°E., 48.8 ft., mkd. T21S R8W S20 BT. A fir, 18" dia., bears S.8½°E., 29.0 ft., mkd. T21S R8W S29 BT. A fir, 16" dia., bears S.24¼°W., 33.1 ft., mkd. T21S R8W S30 BT. A fir, 16" dia., bears N.15°W., 32.1 ft., mkd. T21S R8W S19 BT.</p>	
<p>Gary Smithers - 3/2001 - C.S. File 65/36-13 -----</p>	
Found -	<p>1945 brass cap on iron pipe firmly set on East facing slope. The NE BT &amp; the NW BT were both standing dead Fir in 1945. These BTs are now stumps. We did not look for the BTs taken in 1945 for the sections to the south.</p>
New -	<p>BTs taken by BLM in April 2000, Coos Bay District Rehabilitation not yet approved: (Rec'd 4/2003, DCSO) 18" D.Fir, S.8½°E., 29.0 ft. with scribes visible &amp; BLM tag. 14" D.Fir, S.24¼°W., 33.1 ft. with scribed visible &amp; BLM tag. 16" D.Fir, N.15°W., 32.1 ft. with scribed visible &amp; BLM tag. 14" D.Fir, N.51½°E., 48.8 ft. with scribed visible &amp; BLM tag.</p>
Set -	<p>6 ft. galvanized fence post alongside with top painted red.</p>
<p>Fd. Ok by Ron Rice - 2/19/2003 - C.S. File 65/45-5</p>	
<p>Ron Rice - 3/27/2006 - C.S. File 65/58-11 -----</p>	
<p>BTs found as reported, added a 5½" galvanized steel post is set adjacent to corner. All BTs have red painted bands &amp; yellow BT tags.</p>	