

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 876)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on N face from which:
No witness trees.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11418)

S.89°48'W., bet. secs. 20 & 29
38.895 chains
Set an iron post, 3' long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked:
W C
1/4 S 20
S 29
1945

from which
A Fir, 50" dia., bears N.70°W., 46 lks., mkd: WC 1/4 S20 BT.
A Fir, 46" dia., bears S.5°W., 115 lks., mkd: WC 1/4 S29 BT.
39.145 chains
The proportional point for the 1/4 sec. cor. falls on steep insecure ground with bedrock about 4" below surface.

Gary Smithers - 3/2001 - C.S. File 65/36-14

Found - 1945 brass cap on iron pipe firmly set on North facing slope.
50" Fir snag, N.70°W., 46 lks. with scribe visible "WC 1/4 S 20 BT"
The 46" Fir at S.5°W., 115 lks. is gone.
New BTs- 9" D.Fir, S.60°E., 9.8 ft. to spike set side center, scribed "WC 1/4 S29 BT" with alum. tag.
10" D.Fir, S.70°W., 3.2 ft to spike set side center, scribed "WC 1/4 S29 BT" with alum. tag.
9" D.Fir, N.60°W., 28.4 ft to spike set side center, scribed "WC 1/4 S20 BT" with alum. tag.
8" D.Fir, N.55°E., 16.8 ft to spike set side center, scribed "WC 1/4 S20 BT" with alum. tag.
Set - 6 ft. galvanized fence post alongside with top painted red.