

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 864)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on W face from which:

Elder, 4" dia., bears N.78°E., 50 lks., mkd: 1/4 S BT.

Elder, 3" dia., bears S.27°W., 25 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11401)

Proportional measurement

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked:

S 4 | S 3

1945

from which

A fir, 36" dia., bears S.64 1/2°E., 48 lks., mkd: 1/4 S3 BT.

A Fir, 22" dia., bears N.47 1/2°W., 36 lks., mkd: 1/4 S4 BT.

Fd. Ok on BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1) ** also set a 6 ft. steel fence post alongside the iron post.**

Daniel W. Baker, LS #1978 - For: International Paper Co. - Oct. 25, 1984 - M 97-51 & C.S. File 58/289-3K

Found - 1" iron pipe with GLO brass cap "1945"

42" Fir stump, S.63 1/2°E., 31.6 ft., closed face, 1945 BT.

21" Fir stump, N.45 1/2°W., 23.7 ft., closed face, 1945 BT.

New BTs- 7" Fir N.70°E., 18.2 ft., scribed 1/4 S3 BT.

7" Fir N.60 1/2°W., 14.5 ft., scribed 1/4 S4 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2285, surveyed Aug. 2009/ Feb. 2010 (DCSO records BLM plat 2011 & Vol. 56 Page(s) 22263-65)

The 1/4 sec. cor of secs. 3 & 4, reestablished by Price & Rigby in 1945, utilized by Glenn, et al., in 1967, and rehabilitated by Baker, PLS No. 1978. in 1984; monumented with on iron post, 1" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs mkd. by Price and Rigby
continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A burned decayed fir stump, 37" dia., bears S.64½°E., 31.7 ft., no marks visible.
A burned decayed fir stump, size indeterminate, bears N.47½°W., 23.8 ft. with a healed blaze fallen off stump and the remains of the BTs mkd. Baker, PLS 1978
A fir snag, 7" dia., bears N.68°E., 17.9 ft., with scribe marks ¼ S3 visible on open decayed blaze.
A fir snag, 8" dia.. bears N.63°W., 14.5 ft., with a healed blaze.
and new bearing trees
A fir, 13" dia., bears S.85°E., 9.0 ft., mkd. ¼ S3 BT.
A fir. 21" dia., bears S.55½°W., 9.3 ft., mkd. ¼ S4 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.
A steel fence post with a USFS tag is alongside the cor.
Corner is located S., 40 ft. from a sharp spur, 40 ft. wide, nearly level, slopes S.70°W.