

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 852-3)

-----  
Set post 6" dia., 4 ft. long with marked stone 12" in ground for corner to secs. 10, 11, 14, & 15, marked T21S, S 11 on NE, R8W, S 14 on SE, S 15 on SW, S 10 on NW face with 2 notches on E & 4 on S edge from which:

- Fir, 30" dia., bears N.29°E., 39 lks., mkd: T21S R8W S11 BT.
- Hemlock, 16" dia., bears S.43°E., 39 lks., mkd: T21S R8W S14 BT.
- Hemlock, 14" dia., bears S.50°W., 10 lks., mkd: T21S R8W S15 BT.
- Fir, 14" dia., bears N.33°W., 23 lks., mkd: T21S R8W S10 BT.

BLM dependent resurvey by Marvin J. Lytle, Palmer Norseth, Thomas A. Tillman, Raymond M. Bicknell, Joseph S. Gawron, and Hans W. Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952 thru Oct. 1954 - (DCSO recs. Vol. 30 Page(s) 12579)

-----  
The cor. of secs. 10, 11, 14, & 15, determined at record bearing & dist. from the remaining OBTs, as follows:

- A Fir, 40" dia., bears N.29°E., 39 lks., with illegible scribe marks visible on burned face of blaze.
- A Hemlock, 22" dia., bears S.50°W., 10 lks., with partial scribe marks visible on opened blaze.
- A Fir stump, 18" dia., bears N.33°W., 23 lks., with blaze rotted away.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 26" in the ground, with brass cap marked:

	T21S	R8W
	<u>S 10</u>	<u>S 11</u>
_____	S 15	S 14
	1952	

from which new BTS:

- A Cedar, 19" dia., bears N.56½°E., 76 lks., mkd: T21S R8W S11 BT.
- A Hemlock, 21" dia., bears S.54½°E., 49 lks., mkd: T21S R8W S14 BT.
- A Fir, 48" dia., bears S.35°W., 128 lks., mkd: T21S R8W S15 BT.
- A Fir, 45" dia., bears N.23°W., 73 lks., mkd: T21S R8W S10 BT.

continued next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)

-----  
The corner of secs. 10, 11, 14, & 15, monumented with an iron post, 2" dia., firmly set, projecting 4" above ground, with properly marked brass cap, from which

A hemlock, 25" dia., bears S.50°W., 10 lks., no marks remaining on burned blaze.

A root hole, bears N.56½°E., 76 lks., with a down cedar alongside, 20" dia., with scribe marks T21S R8W S11 BT visible on open blaze.

A hemlock snag, 2 1" dia., bears S.54½°E., 49 lks., with scribe marks T21S R8W S14 BT visible on open blaze.

A fir stump, 48" dia., bears S.35°W., 128 lks., with scribe marks T21S R8W S15 BT visible on open blaze.

A fir stump 60" dia., N.23°W., 73 lks., no marks remaining on burned out blaze.

and a new BT

A fir stump, 25" dia., bears N.23°E., 41 lks., mkd: T21S R8W S11 BT.

Set a 6 ft. steel fence post alongside the iron post.\*\*

Gary Smithers - For: Roseburg Resources Co. - Aug. 2006 - M151-44

-----  
Found - 1952 BLM brass cap, DCSO recs. Vol 30 page 12579  
11" D.Fir S.62°W., 11.5 ft. healed face

Other accessories of record are still present but are in bad condition

New BTs- 13" D.Fir N.1°W., 10.3 ft. to spike side center  
scribe T21 R8 S10 BT

11" D.Fir N.71°E., 6.4 ft. to spike side center  
scribe T21 R8 S11 BT

18" D.Fir S.41°E., 19.9 ft. to spike side center  
scribe T21 R8 S14 BT

BLM Corrective Dependent resurvey by Aaron M. Graham, Cadastral Surveyor, under Group #2150, surveyed Sept. 2006/April 2007 - (DCSO rec. Vol. 56 Page 22107 and BLM Plat T21-8 2010-1)

-----  
The cor. of secs. 10, 11, 14, and 15, perpetuated by Lytle et. al., in 1952-54; monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd. continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an original BT  
A decayed hemlock stump, size indeterminate, bears S.50°W., 6.6 ft., no marks visible.  
and the remains of the BTs mkd. by Lytle, et al.  
A roothole bears N.56½°E., 50.2 ft., alongside of which is a down cedar, 20" dia., no marks visible.  
A fir stump, 42" dia., bears S.35°W., 84.5 ft., with scribe marks R8W S15 BT visible on detached unhealed blaze.  
A fir stump, 48" dia., bears N.23°W., 48.2 ft., no marks visible.  
and the remains of a BT mkd. by Glenn and Jelley in 1967  
A decayed fir stump, 24" dia., bears N.21½°E., 25.8 ft. with scribe marks 8 S11 BT and other illegible scribe marks visible on open blaze. (Record, N.23°E., 27.1 ft)  
and BTs mkd. by Smither, in 2006  
A fir, 13" dia., bears N.1°E., 9.8 ft., with scribe marks T21 R8 S10 BT visible on unhealed blaze.  
A fir, 11" dia., bears N.71¾°E., 6.4 ft., with scribe marks T21 R8 S11 BT visible on unhealed blaze.  
A fir, 17" dia., bears S.43½°E., 19.4 ft., with scribe marks T21 R8 S14 BT visible on unhealed blaze.  
and the remains of a BT mkd. by person(s) unknown and reported by Smither in 2006  
A fir, 10" dia., bears S.59½°W., 11.3 ft., with a healed blaze. A steel fence post is alongside the cor.  
Corner is located on a spur ridge, slopes N.