

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 852)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 on N face from which:

Alder, 10" dia., bears S.49°E., 10 lks., mkd: 1/4 S BT.

Alder, 9" dia., bears N.20°W., 19 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Marvin J. Lytle, Palmer Norseth, Thomas A. Tillman, Raymond M. Bicknell, Joseph S. Gawron, and Hans W. Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952 thru Oct. 1954 - (DCSO recs. Vol. 30 Page(s) 12576)

Point for the 1/4 sec. cor. of secs. 14 & 23, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

1/4 $\frac{S\ 14}{S\ 23}$
1954

from which

A Fir, 15" dia., bears N.44°E., 48 lks., mkd: 1/4 S14 BT.

A Fir, 50" dia., bears S.53 1/2°W., 55 lks., mkd: 1/4 S23 BT.

Troy Rambo - June 2001 - C.S. File 65/37-22A

Found - 1954 GLO brass cap, from which
A 16" DF with visible scribes - bears N.16°E., 11.9 ft. (Scribed by person(s) unknown recently)
13" DF with visible scribes - bears S.40 1/2°E., 26.4 ft. (Scribed by person(s) unknown recently)

Scribed- "1/4 S14 BT" on an 18" DF - bears N.75°E., 14.1 ft.

"1/4 S23 BT" on a 17" DF - bears N.89°W., 12.0 ft.

Note - The record BTs are now rotten stumps

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20743)

The 1/4 sec. cor. of secs. 14 and 23, monumented with an iron post, 1 in. diam., firmly set, projecting 2" above the ground, with brass cap (properly) mkd.

from which the remains of BTS mkd. by Lytle, et. all

A decayed fir stump, size indeterminate, bears N.44°E., 31.7 ft., no marks visible.

A fir stump, 70" dia., bears S.53 1/4°E., 36.3 ft., with a healed blaze. (Record, S.53 1/2°W.)

and new bearing trees

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 15" dia., bears N.16°E., 11.9 ft., mkd. ¼ S14 BT.
A fir, 13" dia., bears S.40½°E., 26.4 ft., mkd. ¼ S23 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,
under Group #2115, surveyed January/May 2007 (DCSO records
Vol. 56 Page(s) 22068-9)

The ¼ sec. cor. of secs. 14 & 23, monumented with an iron
post, 1" dia., firmly set, projecting 2" above ground, with
brass cap (properly) mkd.
from which the remains of the BTs mkd. by Lytle, et al., in
1952-54

A decayed fir stump, size indeterminate, bears N.44°E.,
31.7 ft., no marks visible.

A fir stump, 70" dia., bears S.53¼°E., 36.3 ft., no marks
visible.

and bearing trees mkd. by Graham in 1999-2000

A fir, 17" dia., bears N.16°E., 11.9 ft., with a healed
blaze.

A fir, 14" dia., bears S.40½°E., 26.4 ft., with a healed
blaze.

and BTs mkd. by Rambo, in 2001

A fir, 20" dia., bears N.74¾°E., 13.9 ft., with illegible
scribe marks visible on partially healed blaze and an
aluminum nail on the left side center.

A fir, 18" dia., bears N.88¾°W., 12.2 ft., with illegible
scribe marks visible on pitched-over partially healed
blaze and an aluminum nail on the left side center.

Aluminum fence post alongside the cor.

Corner is located on a bench on a SE. slope.