

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 841-2)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 on W face from which:

- Cedar, 30" dia., bears S.60°E., 41 lks., mkd: 1/4 S BT.
- Cedar, 18" dia., bears N.20°W., 15 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Marvin J. Lytle, Palmer Norseth, Thomas A. Tillman, Raymond M. Bicknell, Joseph S. Gawron, and Hans W. Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952 thru Oct. 1954 - (DCSO recs. Vol. 30 Page(s) 12561)

Point for the 1/4 sec. cor. of secs. 23 & 24, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

1/4
S 23 | S 24
1954

from which

- A Cedar, 22" dia., bears N.48°E., 17 lks., mkd: 1/4 S24 BT.
- A Cedar, 18" dia., bears S.4 1/4°W., 88 lks., mkd: 1/4 S23 BT.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20738-9)

The 1/4 sec. cor. of secs. 23 and 24, monumented with an iron post, 1" dia., firmly set, projecting 6" above the ground, with brass cap (properly) mkd.

from which the remains of BTs mkd. by Lytle, et. all

- A burned cedar stump, 28" dia., bears N.48°E., 11.2 ft., with scribe marks 1/4 S24 BT visible on partially opened blaze.

- A burned cedar stump, 26" dia., bears N.4 1/4°W., 58.1 ft., with a healed blaze.

and new bearing trees

- A fir, 15" dia., bears N.83 1/2°E., 9.1 ft., mkd. 1/4 S24 BT.
- A fir, 23" dia., bears S.34°W., 7.5 ft., mkd. 1/4 S23 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2115, surveyed January/May 2007 (DCSO records Vol. 56 Page(s) 22060-1)

The 1/4 sec. cor. of secs. 23 & 24, monumented with an iron post, 1" dia., firmly set, projecting 9" above ground, with brass cap (properly) mkd. continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the bearing trees mkd. by Lytle, et al., in 1952-54

A burned cedar stump, 26" dia., bears N.48°E., 11.2 ft., with scribe marks $\frac{1}{4}$ S24 BT visible on unhealed blaze and chainsaw marks BI.

A burned cedar stump, 25" dia., bears N.4 $\frac{1}{4}$ °W., 59.4 ft., no marks visible. (Record, 58.1 ft.) Tree is located on the easterly cut bank of an overgrown dirt road, 8 ft. wide, bears N.35°W. and S.50°E.

and bearing trees mkd. by Graham in 1999-2000

A fir, 17" dia., bears N.83 $\frac{1}{2}$ °E., 9.1 ft., with a healed blaze.

A fir, 25" dia., bears S.34°W., 7.5 ft., with a healed blaze.