

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 841)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for ¼ sec. corner marked ¼ S on N face from which:

Cedar, 10" dia., bears N.31°E., 10 lks., mkd: ¼ S BT.

Hemlock, 12" dia., bears S.25°W., 8 lks., mkd: ¼ S BT.

BLM dependent resurvey by Marvin J. Lytle, Palmer Norseth, Thomas A. Tillman, Raymond M. Bicknell, Joseph S. Gawron, and Hans W. Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952 thru Oct. 1954 - (DCSO recs. Vol. 30 Page(s) 12560)

Point for the ¼ sec. cor. of secs. 24 & 25, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 30" in the ground with brass cap marked: ¼ $\frac{S\ 24}{S\ 25}$

1952

from which

A Fir, 40" dia., bears N.58½°E., 56 lks., mkd: ¼ S24 BT.

A Fir, 41" dia., bears S.28½°E., 48 lks., mkd: ¼ S25 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - April/May 1968 - C.S. File 54/67

Found - 1952 GLO brass cap, properly marked.

40" Fir, now burned out shell of stump, N.58½°E., 37.0 ft.

41" Fir, now stump, tipped out, S.28½°E., 31.7 ft., shows good scar.

New BTs- 9" Hemlock N.72°W., 37.4 ft. mkd: ¼ S24 CS BT.

7" Hemlock S.12°E., 54.1 ft., mkd: ¼ S25 CS BT.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20738)

The ¼ sec. cor. of secs. 24 & 25, monumented with an iron post, 1" dia., firmly set, flush with ground, with brass cap (properly) mkd.

from which the remains of BTs mkd. by Lytle, et. all

A fir stump, size indeterminate, bears N.58½°E., 35.0 ft., no marks visible. (Record, 37.0 ft.)

An uprooted fir stump, bears S.28½°E., 31.7 ft., with a healed blaze. continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and new bearing trees
A fir, 11" dia., bears S.74°E., 10.5 ft., mkd. ¼ S25 BT.
A fir, 14" dia., bears N.38°W., 14.6 ft., mkd. ¼ S24 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,
under Group #2115, surveyed January/May 2007 (DCSO records
Vol. 56 Page(s) 22059-60)

The ¼ sec. cor. of secs. 24 & 25, monumented with an iron
post, 1" dia., firmly set, with top flush with the surface of
the ground, with brass cap (properly) mkd.
from which the remains of the bearing trees mkd. by Lytle, et
al., in 1952-54
A hollow burned decayed fir stump, size indeterminate,
bears N.58½°E., 37.0 ft., no marks visible. (Record,
35.0 ft.)
A roothole bears S.28½°E., 31.7 ft., alongside of which is
a down stump, 40" dia., with a healed blaze.
and bearing trees mkd. by Graham in 1999-2000
A fir, 11" dia., bears S.74°E., 10.5 ft., with a healed
blaze.
A fir, 16" dia., bears N.38°W., 14.6 ft., with a healed
blaze.