

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 846)

Set post 4" dia., 4 ft. long with marked stone 12" in ground for ¼ sec. cor. marked ¼ on N face from which:

Fir, 2½" dia., bears N.47°W., 55 lks., mkd: ¼ S BT.

Fir, 3" dia., bears S.42°E., 50 lks., mkd: ¼ S BT.

BLM dependent resurvey by Marvin J. Lytle, Palmer Norseth, Thomas A. Tillman, Raymond M. Bicknell, Joseph S. Gawron, and Hans W. Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952 thru Oct. 1954 - (DCSO recs. Vol. 30 Page(s) 12566)

Point for the ¼ sec. cor. of secs. 1 & 12, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼ $\frac{S \ 1}{S \ 12}$

1954

from which

A Cedar, 36" dia., bears N.47°W., 30 lks., mkd: ¼ S1 BT.

A Fir, 75" dia., bears S.14°E., 24 lks., mkd: ¼ S12 BT.

BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)

The ¼ cor. of secs. 1 & 12, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly marked) from which BTs mkd in 1954

A Cedar, 36" dia., bears N.49°W., 25 lks., no marks remaining on decayed blaze. (rec. N.47°W. 30 lks.)

A Fir stump, 75" dia., bears S.14°E., 29 lks., with scribe marks ¼ S12 BT visible on open blaze. (Rec. 24 lks.)

and a new BT

An Alder, 8" dia., bears N.55°W., 87 lks., mkd: ¼ S1 BT.

Set a 6 ft. steel fence post alongside the iron post.

Les Roberts - For: International Paper Co. - June 26, 1981 - M 88-22

Found - Brass cap (GLO)

36" Cedar, bears N.49½°W., 16.3 ft. (burned face) 1954

60" Fir, bears S.17½°E., 18.4 ft. (scribe vis.) 1954

CONT.

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2720, surveyed Aug./Oct. 2013 - (DCSO records Vol. 58 Page(s) 23121-2)

The ¼ sec. cor. of secs. 1 & 12, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs mkd. by Lytle, et al, in 1952-54

 A decayed fir stump, 80" dia., bears S.14°E., 19.1 ft., with no marks visible.

 A decayed cedar stump, 31" dia., bears N.49°W., 16.5 ft., with no marks visible.

and a bearing tree mkd. by Glenn and Jelley in 1967

 An alder, 15" dia., bears N.55°W., 57.4 ft., with illegible scribe marks visible on a partially healed blaze.

and a new bearing tree

 A fir, 16" dia., bears S. 23° W., 8.8 ft., mkd. ¼ S12 BT.