

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE. Cor. Sec. 1 (NE Tsp. Cor.)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, under Contract #486 dated Aug. 1, 1883 - (DCSO records Vol. 1 Page(s) 455)

Finding that the East bdy. of the tsp. had not been run, I start from the closing cor. to Townships 20 & 21 S., Range 8 West, which is a post, 4" dia., in ground, marked T21S R7W S6 on E.; T21S R8W Sec. 1 CC on SW.; T20S R8W Sec 36 CC on NW. faces, with 6 notches in each edge, from which

Fir 5" dia., bears N.75°E., 11 lks. dist. mkd. T21S R7W S6 BT.

Maple 24" dia., bears N.75°W., 39 lks. dist. mkd. T20S R8W S36 BT CC.

Hemlock 8" dia., bears S.29°W., 14 lks. dist. mkd. T21S R8W S1 BT CC.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #292, Surveyed June/Oct. 1950 (DCSO records Vol. 27 Page(s) 11325)

The cor. of Tps. 20 & 21 S., R. 8 W., on the W. bdy of T21S R7W, is determined from the original bearing trees as follows:

An uprooted Hemlock 8" dia., the stump hole of which bears S.29°W., 14 lks. dist., nearly rotted away.

A Maple 28" dia., bears N.75°W., 39 lks. dist., with axe marks visible at top of blaze, the remainder covered by a Fir log.

At the corner point

Set an iron post, 3 ft. long, 3" dia., 28" in the ground, with brass cap mkd:

| | | |
|--------|--|--------|
| T 20 S | | T 21 S |
| R 8 W | | |
| S 36 | | R 7 W |
| S 1 | | |
| T 21 S | | S 6 |
| 1950 | | |

from which new bearing trees:

A Cedar 40" dia., bears S.77½°W., 29 lks. dist. mkd. T21S R8W S1 BT.

A Fir 60" dia., bears N.43°W., 93 lks. dist. mkd. T20S R8W S36 BT.

BLM Remonumentation of corner by Wm. Glenn; C. Albert White; James E. Jelley, Cadastral Surveyors - Group #'s 350 & 635, Surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16703)

(Cont. Next Page)

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE. Cor. Sec. 1 (NE Tsp. Cor.)

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

The cor. of Tps. 20 & 21 S., R 8 W., on the W. bdy. of T21S R7W, monumented with an iron post 3" dia., firmly set, projecting 7" above ground, with brass cap mkd. in 1950, from which the remains of the original bearing trees:

A Maple snag 22" dia., bears N.75°W., 39 lks. dist. with healed blaze.

and the remains of the bearing trees mkd. in 1950:

A root hole bears S.77½°W., 29 lks. dist. with a down Cedar alongside, 40" dia., with fragmentary scribe marks visible on partially healed blaze.

A burned and sawed Fir stump 75" dia., bears N.43°W., 93 lks. dist. with scribe marks T20S R8W S36 BT visible on open blaze.

and a new bearing tree:

A Hemlock 14" dia., bears S.29¼°W., 80 lks. dist. mkd. T21S R8W S1 BT.

Set a 6 ft. steel fence post alongside the iron post.

Ronald L. Rice - For: Oxbow Timber 1 LLC - May 2014 - C.S. File 65/84-4

Found - 1950 GLO brass cap with the following accessories:
75" Fir stump bears N.43°W., 61.4' - no marks
29" Hemlock bears S.29¼°W., 52.8' - healed face
New BTs- 20" Alder bears S.44°E., 25.1' - bark scribed X BT
10" Hemlock bears N.8°W., 20.8' - blazed, scribed T20S R8W S36 BT
19" Maple bears N.81°W., 22.7' - blazed, scribed T20S R8W S36 BT
Steel post adjacent to corner

FD. as per rec. 8/2016 by Ron Rice, M172-31