

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 970-1)

Set Fir post 4½ ft. long, 5" sq., 24" in the ground on hill side sloping South for cor. to secs. 19, 20, 29 & 30. Marked T21S S20 on the NE, R9W S29 on the SE, S30 on the SW & S19 on the NW, faces with 2 notches on the S & 5 notches on the E edges, from which

A Cedar, 8" dia., bears N.18°30'E., 17 lks., mkd: T21S R9W S20 BT.

A Fir, 16" dia., bears S.61°E., 20 lks., mkd: T21S R9W S29 BT.

A Fir, 18" dia., bears S.12°W., 21 lks., mkd: T21S R9W S30 BT.

A Fir, 18" dia., bears N.20°W., 62 lks., mkd: T21S R9W S19 BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14265)

The cor. of secs. 19, 20, 29 & 30, determined at the record bearing & dist. from the orig. BTs:

A Cedar, 22" dia., bears N.18½°E., 17 lks., with scribe marks S20 visible on partially healed blaze.

A Fir, 23" dia., bears S.61°E., 20 lks. with healed blaze.

A fir, 32" dia., bears S.12°E., 21 lks. with healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T 21 S R 9 W

S 19 | S 20

S 30 | S 29

1967

from which a new BT

A fir, 18" dia., bears N.85°W., 59 lks., mkd: T21S R9W S19 BT.

Fd. Ok by E.M. Wobbe - March 28, 1983 - C.S. File 58/281-2

Gary Smither - Dec. 2000 - C.S. File 65/33-24

Found - 1967 BLM brass cap on iron pipe firmly set flush with ground with 3/8" rebar with International Paper property line tag attached & driven along side the monument approx. 4' high. We drive a 6' steel post near the corner.

continued next page

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. 22" Cedar at N.18½°E., 17 lks., now 36" with healed face & tag.
Orig. 23" Fir at S.61°E., 20 lks., now 34" with healed face & tag.
Orig. 32" Fir at S.12°W., 21 lks., is broken off & rotting away.
18" Fir taken in 1967 at N.85°W., 59 lks., now 22" with healed face & tag.
New BT - 17" Alder, N.15°W., 16.8 ft. to spike driven in side center, mkd: "T21S R9W S19 BT" with BT tag.
No trees remain in SW quad. due to clearcut.

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2721, surveyed June/Aug. 2013 - (DCSO records Vol. 58 Page(s) 23173)

The cor. of secs. 19, 20, 29, and 30, perpetuated by Smither, in 2000; monumented with an iron post, 2½" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees
A cedar stump, 7 ft. high, 39" dia., bears N.18½°E., 11.2 ft., no marks visible.
A fir, 37" dia., bears S.61°E., 13.2 ft., with a healed blaze.
A decayed fir stump, size indeterminate, bears S.12°W., 13.9 ft., with scribe marks T visible on open decayed blaze.
and a bearing tree mkd. by Peterson in 1966-67
A fir, 25" dia., bears N.85°W., 38.9 ft., with a healed blaze.
and a bearing tree mkd. by Smither
An alder, 18" dia., bears N.25½°W., 16.3 ft., with scribe marks T21S R9W S19 BT visible on bark with a spike at the base on right side center.
No suitable trees in sec. 20.
Alongside the cor. is an aluminum fence post.