

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 971)

Set Alder post, 4½ ft. long, 4" sq., 24" in the ground on steep hill side sloping E for ¼ Sec. cor. mkd. ¼ S on the N face, from which

A Hemlock, 8" dia., bears N.18°E., 38 lks., mkd: ¼ S BT.

A Fir, 48" dia., bears S.10°W., 41 lks., mkd: ¼ S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14261)

The ¼ sec. cor. of secs. 20 & 29 determined at the record bearing & distance from the orig. BTs:

A rotted Hemlock stump, 22" dia., bears N.18°E., 38 lks., with scribe marks BT visible on opened blaze.

The root hole of a fallen Fir, 60" dia., bears S.10°W., 41 lks, with healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼ S 20
S 29
T 21 S R 9 W
1966

from which new BTs

An Alder, 5" dia., bears N.60°E., 30 lks., mkd: ¼ S20 BT.

A Hemlock, 6" dia., bears S.71°W., 63 lks., mkd: ¼ S29 BT.