

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 957)

A Fir, 8" dia., I marked West side ¼ S. for ¼ sec. cor., from which
 A Fir, 8" dia., bears N.77°30'E., 23 lks., mkd: ¼ S BT.
 A Fir, 6" dia., bears N.25°W., 58 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey & crew - Oct. 7, 1964 - C.S. File 52/14-143

Found - Hemlock snag (not Fir) N.77½°E., 15.2 ft. good reverse scribing "¼" & "BT" on badly rotted face.
 Did not find corner tree nor NW BT.
Set - Brass cap at cor. mkd: County Surveyor's Office 1964 T21S R9W ¼ S29|S28
 30" Hemlock S.48°5W., 59.0 ft., mkd: ¼ S29 CS BT.
 21" D.Fir N.53°E., 33.2 ft., mkd: ¼ S28 CS BT.
Note - Corner is in draw sloping East, approx. 10 ft. N of bottom.

Fd. & used on BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14249-50)

Clyde Mulkins - For: I.P. Timberlands - Jan./Feb. 1996 - M141-61

Found - 1964 county brass cap.
 33" D.Fir with a healed face bears N.54°E., 34.6 ft. (Rec. N.53¼°E., 50 lks.)
 42" Hemlock with healed face bears S.48½°W. 58.1 ft
New - I scribed "¼ S28 BT" on a 22" Hemlock bears S.50°E., 46.0 ft.
 I bark scribed "¼ S29 BT" on an 11" Alder bears S.28°W., 32.0 ft.
 Corner falls 10 ft. North of creek.