

PRIMARY CORNER DESCRIPTION Sec cor for 33 and 34 only (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 897-98)

Set Fir post 4½ ft. long, 5" sq., 24" in the ground on hill side sloping SE, for cor. to secs. 33, 34, 3 and 4, mkd. T21S S34 on the NE.; R9W S3 on the SE.; T22S S4 on the SW.; and S33 on the NW. faces with 3 notches on the E. and W. edges, from which

- A Maple 8" dia., bears N.22°E., 21 lks. dist. mkd. T21S R9W S34 BT.
- A Fir 24" dia., bears S.73°30'E., 42 lks. dist. mkd. T22S R9W S3 BT.
- A Fir 24" dia., bears S.76°30'W., 65 lks. dist. mkd. T22S R9W S4 BT.
- A Fir 24" dia., bears N.88°W., 59 lks. dist. mkd. T21S R9W S33 BT.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1665-66)

Intersected North bdy. of T., 355 lks. W. of the corner to secs. 3, 4, 33 and 34, T21S, which is a post, 2½ ft. above ground 4" sq., firmly set, mkd. T21S S34 on the NE.; R9W S3 on the SE.; T22S S4 on the SW.; and S33 on the N. faces with 3 notches on the E. and W. edges, from which

- A Maple 8" dia., N.22°E., 21 lks. mkd. T21S R9W S34 BT.
- A Maple 16" dia., bears S.73°30'E., 42 lks. dist. mkd. T22S R9W S3 BT.
- A Fir 24" dia., N.88°W., 59 lks. mkd. T21S R9W S33 BT.
- A Fir 24" dia. bears S.76°W., 65 lks. dist.

I destroyed the marks on tree S. of line.

V. W. Hosford - For: Evans Products Co. - Aug. 1954 - C.S. File 41/292 and M 10-80

The corner 33|34, T21S R9W is marked by a 3/4" Iron pipe. The original NE and SE BTs are gone. The original SW BT is a 32" stump with overgrown scar. The original NW BT is living and shows a burned out scar.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - Oct. 5 1971 - C.S. File 53/66-131

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec cor for 33 and 34 only (South)

Alias	Description

Found - 1" I.P. at corner, unrecorded.
24" D.Fir now 46" stump, N.88°W., 38.9 ft., opened for scribe "9W" and other marks.
24" D.Fir now 40" stump S.76½°W., 42.9 ft. shows axe work.
No trace of SE BT.
New BTs -6" D.Fir N.53°W., 4.0 ft. scribed S33 CS BT.
6" Maple N.24°E., 12.9 ft. scribed S34 CS BT.
6" D.Fir S.80°E., 7.0 ft. scribed S3 CS BT.
This corner lies about 80 ft. E. of skid road on ridge top.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1367, surveyed April/June 1987 - (DCSO records Vol. 48 Page(s) 18430)

The cor. of secs. 33 and 34 only, perpetuated and recorded by Powell in 1971, monumented with an iron post 1¼" dia., firmly set, projecting 14" above ground, (alongside of which is an iron pipe, 1" dia., firmly set, projecting 4" above ground), with brass cap mkd: COUNTY SURVEYORS OFFICE

T 21 S R 9 W
S 33 | S 34
S 3
1971

from which the remains of an original bearing tree
A sawed Fir stump 36" dia., bears N.88°W., 59 lks. dist., with scribe marks T21 visible on opened blaze.
and bearing trees mkd. by Powell
An Alder 10" dia., bears N.24°E., 19½ lks. dist. with healed blaze.
A Fir 6" dia., bears S.80°E., 10½ lks. dist. with healed blaze.
A Fir 13" dia., bears N.53°W., 6 lks. dist. with healed blaze.
and a new bearing tree
A Fir 10" dia., bears N.18¼°E., 42 lks. dist. mkd. T21S R9W S34 BT.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19857)

Found OK by D. Edwards, June 2000 - M135-6